

# **Visual Pre-Inspection Agreement**

Name: Ben Fergoson	
Name: Ben Fergosan  Current Address 37 Hawatha City/ Province/ Postal TORONYD	
Phone # 4(6-278-3574 E-Mail: Ben a Mattandben. Ca.	
Regarding: (Property to be Inspected)  DATE Nov. 17/16 Time: 8:45am	
Address: 37 Hiawatha Rd. Unit # City: Toronto	
Between the above named Customer and the undersigned, an Independently owned and operated Franchisee of Lighthous Inspections ("Inspector").  For a Fee of \$	iy. ea ed ng ay
are limited in liability to the fee paid for the inspection services and Report in the event that the Client or third party claims that Inspector is in any way liable for negligently performing the inspection. Client hereby agrees to indemnify, defend and hold harmless Inspector and Lighthous Inspections if any third party brings a claim relating to this Inspection Report.  Notice: The Client acknowledges and agrees that any claim(s) or complaint(s) arising out of or related to this Visual Inspection shall be reported to Inspector, in writing within ten (10) days of its detection in order to allow the Inspector the opportunity to re-inspect that portion of the home in dispurpior to any renovations or repairs relating to the concern in the Report Any claims must be presented within one (1) year from the date of the inspection; Inspector will have no liability for claims presented after this time.	se
Exclusions and Limitations	
The Inspector is limited to a visual inspection of the building only, any areas that are blocked by finishing materials, storage, furniture, or environmental factors are therefore eliminated from the scope of this inspection. The role of the home inspector is as an educator, to provide you with an understanding of the home and it's components. Annual maintenance costs run approximately 3 to 5% of the purchase price.  The Inspector does not assess:	
<ul> <li>Aesthetic or cosmetic concerns (i.e., finishes, odours, cleanliness); Design or adequacy of rooms or the home in general or compliance to UL or CSA standa</li> <li>Quality of workmanship or material that does not affect the structural integrity or safety of the home.</li> <li>Building codes as these are revised on an ongoing basis and are not standard across municipalities. Local building officials assess code compliance</li> <li>Life spans and age of elements and/or components. Indications are estimates only, the inspector cannot guarantee that such items will last for their expected life span, including but not limited to life expectancy and failure of components</li> <li>Attics will rarely be entered, in most cases, the inspector will perform a general inspection from the access hatch, where accessible</li> <li>Ancillary elements including, but not limited to, barbecues, site lighting, solar heating panels, satellite dishes, irrigation systems, security systems, sprinkler systems, central vacuum systems</li> <li>Inspect roofs that are not visible from the ground with binoculars or not accessible from a 13-foot ladder. Inspectors do not walk roofs; to do so may cause leaks or other damage at the time or within months of the inspection and could affect the roof warranty.</li> </ul>	
Please see Page 2 of this Pre-Inspection Agreement.	
© Lighthouse Inspections EACH OFFICE IS INDEPENDENTLY OWNED AND OPERATED	

Page 1 of 2

#### Visual Pre-Inspection Agreement - Page 2

#### The Inspector cannot:

- Move personal belongings, storage or furniture, finishing, carpeting snow, ice, earth, etc., to gain access to hidden areas or to improve visibility of an area
- Determine the presence or absence of environmental or health concerns including, but not limited to: contaminated soil, potable water, radon, lead, UFFI, air quality, mould, mildew, carcinogens or other such hazard
- Operate components or assess utilities that are shut off, winterized, covered, do not respond to normal operating devices or otherwise restricted
- Light pilot lights that are not in functioning order / Ignite or extinguish solid fuel fires
- Perform invasive procedures to investigate a potential defect in construction, for this reason the inspector will often recommend a specialist be brought in to further evaluate components.
- Enter any area which the inspector feels is unsafe for entry, with headroom of less than 3 feet or areas with standing water
- Inspect or evaluate the operation of any underground drainage pipes, footings, etc.
- Operate air conditioning systems if the temperature has fallen below 16 degrees Celsius in the past 24 hours.
- Inspect or evaluate items not permanently installed
- Project operating costs of any components
- · Uniformity or adequacy of heat or cool supply to any rooms
- · Report on sizing or efficiency of heating or air conditioning units
- · Operate automatic safety controls
- · Evaluate or report on telephone, television cable, internet service availability or signal strength
- Report on anything not visible to the inspector, including but not limited to: concealed insulation or vapour barriers, inside walls, floors or ceiling cavities
- Operate heat pump in heat mode when temperature has been above 22 degrees Celsius in the past 24 hours
- Perform formal energy audit or evaluation
- · Report on property lines or encroachments
- · Evaluate or operate digital or computerized thermostats or controls
- · Report on conformance or legality of secondary or basement apartments or finishings
- Determine if a building permit has been issued for any additions or renovations, etc.
- · Observe the interior of chimney flues, fire chambers, heat exchangers, humidifiers or filters
- · Report on the presence or absence of wood destroying insects
- Make assurances of a dry basement or crawl space
- If building is covered by condominium management, determine which items are the responsibility of the condo or owner, we rely on the homeowner for this information

#### The Inspector is not required to:

- · Evaluate fountains, spas, saunas/steam rooms, hot tubs, swimming pools, septic, cisterns, water treatment systems etc.,
- Report on the cause of observed damage or recommend repair techniques or contractors
- Evaluate shower pans for leakage
- · Report on anything other than output from wells, the inspector shall run the water from inside to determine functional flow
- Determine whether waste lines are municipal or private, and is often required to rely on the homeowner for this information
- Test or operate any over current devices except Ground Fault Circuit Interrupters
- Evaluate geological conditions, soil conditions, recreational facilities, or outbuildings other than primary garages and carports
- Operate trash compactors, individual room and window cooling units or evaluate the effectiveness of anti-siphon devices

Cash

- Test carbon monoxide detectors or smoke detectors by any means other than the test button
- Evaluate clearances around heat sources

Payment received by (circle)

Agreement is acknowledged. Receipt of a copy of the is an independently owned and operated business that	Pre-Inspection Agreement is also ack thas been granted license to use the l pisor is not involved in the day to-day a	Acceptance and understanding of this Visual Pre-Inspection mowledged. Inspector providing the home inspection service and Report Lighthouse inspections names, trademarks and methods. In retaining activities and is in no way responsible for the Inspector's services or mpany.
	0//	Nov/7/2016
Signature: Client or Client's Representative		Date
Representative Signature	Operating as: Address: Phone Number:	Michael Tital  Elite Team Home Inspections Limited  Lighthouse Inspections Mississauga East  2325 Hurontario St. Suite 322, Mississauga  905-271-6381
Fee, including inspection and report ag	Payment Information / reed to above and other service	Receipt 452.00

Cheque # © Lighthouse Inspections EACH OFFICE IS INDEPENDENTLY OWNED AND OPERATED

# **Lighthouse Home Inspection Report**

The main purpose of the Lighthouse home inspection is to provide clients with a better understanding as to the general condition of the home. A visual inspection of the building and its immediate grounds has been conducted in accordance with the pre-inspection agreement and the standards of practice in the home inspection industry. The facing pages outline general information and the Lighthouse standard of practice. This information forms an integral component of the inspection results and should be reviewed thoroughly in conjunction with the personalized sections of the report. The home inspection report is confidential and was prepared for the exclusive use of the client as identified in the agreement.

Summary				
Address of Inspection: 37 Hiawatha Rd. Torento				
Date of Inspection: Nov. 17/16 Approximate	start time: 2:07A.M.P.M. (circle) stop time 12:0A.M.P.M.			
Recent WEATHER conditions:	Rain past 3 days: Yes Light No			
Weather at start of inspection: clear + s	unny Ground Condition ≥ Wet Dry Snow			
Approximate outside temperature during the inspection	C. & prior to inspectionC.			
Front of Building facing:NorthSouthEast \( \subseteq \text{We} \)	st In Attendance:ClientHomeownerOther			
General Accessibility:Excessive storageConst	ruction in progressSystems winterized			
Utilities turned offOccupied room or section	Access deniedOther			
Reference: Iten	n & Page Number			
General Structure & Roofing	Basement & Crawl Space 22			
Ohimanaya & Boot Dyningson	Water Penetration & Internal Structure (24)			
Chimneys & Roof Drainage 6	Water Penetration & Internal Structure (24)			
Vehicle Parking 8	Laundry & Wet Bar 26			
Exterior 10	Kitchen and Appliances 28			
Additions 12	Bathrooms 30			
Grounds & Air Conditioning 14	Fireplaces & Common Safety Devices 32			
Grounds & Air Conditioning 14	Fireplaces & Common Safety Devices			
Electrical (16)	General Interior 34			
Plumbing (18)	Attic & Ventilation 36			
Heating (20)	Insulation 38			

Please note some deficiencies in the home may not be included on this summary page. Items that do not pose immediate safety hazards may be observed and omitted from this page.

The overall, general	al habitability o	if this ḥome, taking	into account the ent	ire report, is in the opi	nion of the inspector:
Good	Solid	home	· Some	typical	maintenance
issues	and	other	repairs	netted.	
If you have any c	uestions, we	encourage you t	o confact your insp	ector at	271.0804

Page 2 of 38

# **General Structure & Roofing**

Building Style  Detached	Roof Style(s) Shed Hin Flat
Semi- Detached	Roof Style(s)GableShedHipFlatRidgePitched
Townhouse Condominium / Apartment	Roof Covering(s)Asphalt ShinglesTar & Gravel Wood ShinglesMetalRolledSlate / Clay Tiles
Bungalow 2 Storey + Loft Split Level	Rubberized Membrane  Estimated life span:YoungerMid-life
2nd floor extends out beyond 1st floor	Older or End of useful life Number of layers
Estimated Age:Under 10 yearsover 70 years	Inspection Method: From ground with binoculars  from a window from roof edge  Identified the following conditions:  From ground with binoculars  From ground with binoculars  From ground with binoculars  From ground with binoculars
Occupancy: Occupied Vacant Staged	Identified the following conditions:    Solit   Factor
General Construction:Wood FrameMasonry	particulate releasing dried brittle / crumbling
	broken / missing partsother roof covering deteriorationexcessive moss or mold growing on roofparts hed_flatwaves and dips noted between structural members, see ATTIC
Flashing  MaterialNone notedunknown metal	waves and dips noted between structural members, see ATTIC section of report
Rubberized membraneGalvanizedMaterial not determinedPieces damaged / loosePieces missingPieces missing	Younger roof covering indicators:cleanfresh colourlaying smooth
From interior, stains or wet spots indicate possible leaking at or near flashing Limitations:% not visible	Inspection Limitations: Theportion of roof was not visible to the inspector and should be inspected by a roofing contractor to determine condition
Course of Action: add flashing as	Roofing is mostly snow coveredFlat roof is covered by decking and could not be inspected
	Leaks see Moisture and water penetration in ATTIC section of report.
Skylights & Roof Windows  None noted on exterior of house  # of units noted Type:DomedFlushRoof Curb identified	Course of Action Recommend roofing contractor reroofRecommend roofer
Material:glassplasticunknown materialPatching noted around unit on roof	Soffit & Fascia
Evidence of condensation noted Caulking around unit:appears adequatemissing or damaged, recommend repair	Soffit:aluminumplasticPaintedPaint deterioratedMouldRottedlooseevidence of leaksrustcorrosion
Defects noted:Cracked Glazing:double or triplesingle, requires repair Skylights and Roof Windows are also identified on Interior section	Fascia:aluminumwoodplasticPaintedPaint deterioratedMouldRottedlooseevidence of leaksrustcorrosion
of report.	
Additional Comments or Issues:	wood soffit + faccia deteriorate at rear gable (repair + cap)

Course of Action: Have a roofing or other appropriate contractor repair any deficiencies noted above.

# Chimneys & Roof Drainage

Chimney	Drainage
BrickBlockStoneMetal	Nothing noted to direct roof run off
Chimney is covered, limiting inspection	On roof diverters were noted
Clearance sufficient above roof	
Decommissioned chimney; non-standard, have removed/sealed	Gutters and Downspouts
Chimney saddle on roof above chimney  Number of chimney(s)	dutters and Downspouts
High Efficiency exhaust	Material: AluminumCopperPlasticOther metal
Missing or loose mortar Cracks	
Flue linerobservedcrackedmissing	Defects:
Clean-out: located basament	LooseBrokenOut of adjustment
Clean-out: located	Remove debris which is sticking out of system Stains over outer gutter edge indicate overflow, system may be
operableUnable to operate, have repaired Clean-outDirtyDamagedBlocked	clogged or undersized
Birty	ologgod of anadiologod
Chimney cap / washobservedBroken / damaged	Leaking observed at:
Cap overhanging to protect brick None noted	DrainsDownspoutsCorners of gutters
Rain Cap / Spark Arrester None noted	Diaghayan
Defects Observed:	Discharge: ✓Discharges onto ground
Cracked Loose Damaged	Discharge extended 6 feet from foundation
Deterioratednot visible	
	Discharges into pipe or hole in ground
Flashing at chimney secure	Did Did not determine where pipe exits
LooseDamaged, repair / reseal / replace	Recommend change to ground discharge
BEFORE USE, have chimney sweep clean, further evaluate &	Sufficient number of downspouts
repair as needed.	Add downspout at:FrontRearLeftRight side
Temporary / non-standard repair observed, recommend	Downspouts blocked
mason evaluate and repair as needed.	
Course of Action:	Gutters:RustyHolding water (adjust)
Course of Action:	Rustynotding water (adjust)Clean gutters
Futurian Vantilation	oroan gattoro
Exterior Ventilation	
Types:Gable End VentsRidge VentSoffit Vent	Course of Action:
Windows Attic fan(s) Roof vents Turbines	Recommend add / adjust splash blocks
Self opening & closing louvered vents.	Recommend add extensions to downspouts to direct water
	farther away from foundation
Side Walls:	Recommend redirect water discharge off lower roof – connect
No evidence noted to indicate need to increase ventilationSpalling brickMould/mildew spores	with lower gutters or direct to ground discharge
Peeling or stained paint on exterior siding seems to indicate more	Downspout missing, re-install
ventilation is needed in side walls for the house to breathe better	Water penetration noted, make appropriate repairs
Course of Assigns	Have the appropriate type of contractor make repairs as needed
Course of Action: Recommend adding ventilation	to the above components
Troophilliplia adding volulation	
Additional Comments or Issues:	

Course of Action: Have a roofing, masonry, or other appropriate contractor evaluate and repair as needed.

## **Vehicle Parking**

Driveway	Garage
None noted AsphaltConcreteStone or gravel	None Noted
Interlock	Fating And Clark
Defects noted:	Estimated Size:Car(s) Bays are: side by sidetandem
Depressions or holes pose a trip or safety hazard and should	Attachedliving space above
be corrected.	
Slope to building directing water to building or into garage,	Semi-detachedDetached Interior accessed:YesNo because
should be corrected.	Visibility limited by:Parked carStorage
Trench drain should be added across width of garage	Floors Comprete Applied Diet
Crumbled/damaged surface may indicate water damage from under driveway surface.	Floor:ConcreteAsphaltDirt
undor anyoway danado.	Defects: Cracks Depressions Oil stained
Course of Action:	Deteriorated surfaces
	Walls:MasonryWood framed
	Framingexposed to viewblocked by storage / walls finished
Other Parking Area	Exterior finishes deteriorated, replace
None notedNot determinedOn street	Automobile doors:Overhead Swinging
Off street Common parking area	Number:such doorsOperatedNot-operated, because
Canada	Electric opener noted
Carport Mone Noted	
Z_woule worked	operatednot operated, becausedid not stop or
Size: Car(s)	reverse, as expectedAdjust sensor
AttachedSemi-detachedDetached	Missing safety cables inside of overhead garage doors
Visibility clear	springs, have contractor install.
Visibility obstructed by:Parked carStorage	Man dearn into house to exterior
Floor:ConcreteAsphaltDirt	Man doors:into houseto exterior #doorsoperated
Normal condition	Replace weather sealRequires proper step(s)
Defects:CracksDepressionsOil Stained	Self Closing door?YesNoAdd
Deteriorate surfaces	Not operated, because
Walls:Vertical supports onlyOpen to weather	Results:
Enclosed on #sides	Windows: None fixed operational
	Not tested, because
Roof underside:Framing and sheathing exposed to view	Results:
from insideStored items restrict viewing	Parking and a second and a second at the sec
Water Penetration:Water stains	Roof underside:Framing and sheathing exposed to view from inside Drywall Stored items restrict viewing
Water leaking through Damaged members	TOTAL MORAL DISYNAL COLORED RESULTS RESULTS AND
	Enclosed attic:AccessNo access
Attic:Enclosed attic:AccessNo access	Enclosed attic:AccessNo access Entered YesNo
EnteredYesNo	Water Department Water states
	Water Penetration:Water stains notedWater leaking throughDamaged members
Course of Action:	
	Gas-Proofing: Seal any openings in the finishing materials to
	minimize the potential for gas entry into the home
Additional Comments or Issues:	
TAMINOTIAL COMMINGRICO OF 100465.	

Course of Action: Have a home improvement or other appropriate contractor evaluate and repair as needed.

## **Exterior**

ſ	Wall Finishes	Foundation Walls	
	Location:All Main FloorUpper floor	Poured Concrete Block & Mortar Stone & Mortar Brick & Mortar Wood Stucco_over_unknown Nostly None Visible Defects: Cracks observed were smaller, monitor over time Larger cracks were observed, recommend repair Vines, shrubs, trees or other planting obscuring the view of the foundation. These plantings will restrict the inspection scope and may be hiding significant defects.  Structural No major structural defect evidence was noted, appears in normal condition for its age Major structural defect evidence was noted, as described:  Course of Action: Doors Sliding glass Metal Wood fiberglass / composite Open & close as expected	
	Storms Screens Some may be missing  Loose or missing glazing should be replaced  Loose or missing caulk, have recaulked  Trim, Observed: Mould Decay / rot	Open & close as expected Need adjustments to operate as expected Broken door or parts need repairing/replacing	
	Re-seal sills Maintenance / repairs required at window frames  Basement window(s):None notedWoodMetalPlastic Sash are locatedhigh near ceiling	Missing/broken hardware to be installed/replaced/repaired.  Reseal frames + 6a se  Storm doors Operated:open & close as expectedDoors require adjustment to operate as expected Trim, Observed:MouldDecay / rot	
	and openinoutslide sideways	Wood to Soil Contactwaswas not observed	
	Window Wells None notedNone notedConcrete UncoveredCovered  Defects:BrokenCrackedCrumbling Flooded Damaged cover	Location:  Course of Action:  Remove all decayed wood and raise any wood structure onto concrete pavers as possible	
	Nater Stains inside windows indicating poor drainage	Storage	
	Course of Action:Recommend adding well for drainageCover should be installed/repaired to keep water outClose down openings for safetyRe-secure to wallGrade in well too high, lower	Excessive storage at side of building, have removedWood piles against building, have removed, may provide home to animals and insects.	
	Additional Comments or Issues:		

Course of Action: Have an engineer, Pest Control or other appropriate contractor rectify any deficiencies noted above

#### **Additions**

	Deck and Balcony
Location: Tront	None noted
ConcretePorch ofwoodconcrete	Location: rear yard
stone with stepswalls enclose area	WoodMetal Concrete
Deteriorated/damaged steps / supports pose safety hazard	y Otema to much
# steps down from porch	# Steps to grade
Step rise(s) too high / uneven, adjust	Too close to grade to look underClose to grade could only see under some sections
Handrails/guardrails:	Sufficiently above grade to get under and look
None noted Recommend add for safety	No access below Blocked byStored items
Loose or unsafe, recommend repair for safety	Plant growthElements(Snow, ice, water)
Railings too low by today's standards, add / adjust for safety	Defects:
	Uneven surfaces pose a trip hazard
Walkways	No bolts noted to attach to house Bolt to framing
None noted	Install missing / additional joist supports
	Support columns not attached to foundation
To Main entry: Concrete Asphalt Pavers	Take steps to reduce sway or deflection noted
Slate Gravel Interlock / brick Uneven/broken surfaces pose trip hazard	Wooden piles / supports below soil, raise above soil level Wood flooring and/or structure deteriorated
onevenionen sundues pose nip nazalu	Improve supports as required
Other walks:ConcreteAsphaltPavers	Lyzyz zakk and ar radaman
Slate Gravel Interlock / brick	Handrails/guardrails:
Uneven/broken surfaces pose trip hazard	None notedRecommend add for safety
	Feel loose Broken Close down openings for safety
Secondary Entry	Railings too low by today's standards, add / adjust for safety
None noted	
Location:	Patio
Concrete slabPorch ofwoodconcrete	None noted
stone with stepswalls enclose area	
Deteriorated/damaged steps / supports pose safety hazard	Location: Pavers Slate Stone Interlock
#steps down from porch Step rise(s) too high / uneven, adjust	Uneven/broken surfaces noted which pose trip hazard
Exterior below grade entry notedrequires proper step(s)	One very broken earliesed when peed the mazard
Requires proper drain	
• •	
Handrails/guardrails:	Retaining Walls
None notedRecommend add for safety	None noted / decorative only
Loose or unsafe, recommend repair for safety	Wooden:Pressure treated
Railings too low by today's standards, add / adjust for safety	Unknown if pressure treatedAppear untreated
	Concrete Block Stone Brick
Fences	Mortar joints observed
	Drainage holes to relieve water pressure from behind the wall
Wood Metal Other	areare not evident.
secure loose weak Broken sections	Defects:
Yard not fully fenced	Buckling Bowing Cracking Leaning
Gate:operatedself-closer install self-closer	Differential displacement Other displacement
X Inspector does not know ownership	
Additional Comments or Issues:	

Course of Action: Have the above noted deficiencies corrected by the appropriate contractor

## **Grounds & Air Conditioning**

Grading	Air Conditioning
Within 6 feet of foundation:	None Noted
Front of house, slopes	e f 1 · 1
towardis relatively level,	Location: right side
Right of house, slopes	and the same of th
toward away from house is relatively level	Brand name on central unit: <u>Goodmah</u>
Left of house, slopes	Tune: Vi Central Air Heat Pump Gas Chiller
Rear of house slopes W/4 due to deck	Type:Central AirHeat PumpGas ChillerElectric Compressor
towardaway from houseis relatively leveltowardaway from houseis relatively level.	Roof or attic mounted (or other) system
Beyond 6 feet:	Ductless Air Conditioning system
Entire lot is relatively level	Water cooling system, recommend replace
Slopes away from house, acceptable	
Slopes towards the house, should be graded away	
X Recommend grading slope to direct water a minimum of 6 feet	In use during inspectionOperated
from foundation to minimize water penetration  General grading should be addressed as larger depressions	Not operated
can pose a trip hazard	(see opposite page for testing limitations)
Ravine lot, potential erosion concerns	(coo opposite page to thomag illimated by
Recommend the following negative effect on the building is	
addressed:	
	Visible portion of equipment appears to be
General grading could not be assessed due to snow.	NewerMidlifeOlder
	or ApproximatelyYears old
Trees, Shrubs, & Plantings	
Trees, shrubs and other plantings near the home should allow the	Central unit appearslevelnot level
home to breathe	Outdoor fan is:obstructed
None noted near house which appear to pose a possible hazard to the house at the present time.	Outdoor grills are:damageddirty  Have all debris removed before use
Planting(s) noted overhanging / touching /near to / climbing on	Compressor isnoisy
house	,
These conditions should be corrected, usually involving cutting back,	Ductwork
pruning or removal of the planting.	in common with heatingindependent from heating.
Other plantings, away from house, should be inspected by	·
client and attended to as needed	Mark!
	With unit running, house seemed to cool
Environmental	slowlyquicklyadequately not at all
Although not required as part of a Home Inspection, some evidence	Course of Actions
noticed by an inspector, which might indicate some environmental hazard, chemical or oil spills:	Course of Action:
· · · · · · · · · · · · · · · · · · ·	
Dead foliage, out of season - looks unusual  Dark stains on soil  Oil slick or stain on water	
Abandoned motor vehicle(s) batteries Paint cans	Individual room units observed
Pipes into the ground may indicate buried storage tanks	operatednot operated
Out of use storage tanks	Results: received coolingdid not receive cooling
Homes of this era may have additional environmental	
hazards/concerns.(i.e., lead, asbestos, etc.) that are not visible to	
the inspector	Course of Action:
Course of Action:	
Recommend further evaluation by an appropriate contractor	
before any renovations of the property.	
Additional Comments or Issues:	

Course of Action: Have a heating / cooling or landscaping contractor evaluate and repair as needed.

## **Electrical**

Г	Main Service Entrance	, Main Distribution Panel		
	Location:	Location basement		
	Service Line: Underground Overhead wires	Service Panel Rated 125 Amps (Too h)		
-	Overhead Contact Hazards observed:	Main Disconnect: 150 Amps \ reduce		
	obstructed / threatened / touched by tree / branches have hydro	Circuit breaker Fuses Knife switch		
e	or a tree surgeon correct situation before damage occurs	Location Main panel box Other		
	<i>Meter</i> Service cable rated: <u>260</u> Amps	Service Size 150 Amps Circuit Breaker Fuses 110-120 volt circuits: (number) 20 15A30A		
	Rated110/120 Volts220/240 Volts	110-120 volt circuits: (number) 20 15A 20A 30A		
	2 W (# wires in service)	220, 240 volt circuits: (number)		
İ	Location: right side	Branch wiring		
١		CopperAluminumKnob & Tube		
	Distribution	BX Cable (Metallic sheathed) Romex (Non-metallic		
l	Outlets, switches, lighting as observed and evaluated, throughout	sheathed)Not determined		
	the home. Random tested outlets, wall switches & installed lighting	As observed:inside panel box Circuits labeled?YesNoSome		
	and found the following evidence:	Circuits labeled? Yes No Southe		
-	no deficiencies were detected3 holes(Says grounded)	Panel has been upgraded from original		
		Sub Panels None noted # noted.		
	Material Copper Aluminum Knob & Tube	Sub Panels None noted# noted, Panel Rated Amps; Service SizeAmps		
-	*Please note that Aluminum and/or Knob and Tube wiring may exist within the	Location		
	homes' system and not be visible to the inspector or reported due to the limited			
	nature of such an inspection. Inspector cannot determine percentage of older wiring.	Defects:		
		More than one wire attached to a circuit protector, have		
	Defects:	evaluated for safety by electrician		
	Ungrounded outletsReversed polarity	Abandoned wire(s)  Connections in panel box		
	Hot Ground reversedDead outlets	Non-standard installation / upgrade, further evaluation		
	Open groundOpen neutralOpen hot	Water stains Rust		
	Open air connections  Missing safety covers on switches, outlets and junction boxes	Dead insects, may indicate cable entry not sealed properly		
(	Loose connections Loose boxes Loose receptacles	Unprotected panel openings, recommend closing down		
(	Lights did not light, missing or broken bulbs Flickering lights	Overloaded circuits Overfused breakers / fuses		
	Switches for which use not determined (frequently noted)	Loose connectionsinto the boxwithin the box		
	Loose hanging wires / otherwise dangerous conditions.	Damaged sheathing Discoloration of wires in panel, may indicate overloaded circuits		
· Comme	Bare bulbs near / touching storage items, possible fire hazard	Panel location non-conforming, needs to be addressed		
	Move wires off heating ducts (secure)	Panel location hori-comorning, hoods to be dudiced a		
	Lighting at staircases is not sufficient In staircases with 3 or more steps, switches are not	Course of Action:		
	located at both the top and bottom of staircase.	Have an electrician install Arc Fault Interrupter (AFCI)		
	Decora style switches and outlets noted throughout system,	protection		
	have checked for proper installation with aluminum wiring	Panel may be overloaded, have evaluated and repaired as		
	Outlets with 2 slots (Older ungrounded style)	needed main circuit  Have an electrician check panel and rectify deficiencies as		
	Non-standard electrical noted			
•	Interior grade wiring noted on exterior	needed.		
	Improper use of electrical cords	General Limitations		
	Course of Action:	X Concealed electrical components cannot be inspected Main disconnect cover could not be removed, common		
	Have an electrician check entire system and rectify	Panel cover could not be removed due to accessibility,		
	deficiencies as needed.	recommend correct Power off insomeall areas		
	ESA certificate may be recommended or required due to	No access to:		
	aluminum or knob and tube wiring	In most cases, grounding termination point is not visible.		
	Additional Comments or Issues:			
	/ IMMINISTRATION OF THE PROPERTY OF THE PROPER			
		Lists and renair entire system as required		
	Course of Action: Have an electrician evaluate and repair entire system as required			

# **Plumbing**

Water Supply	Waste System
Entry Location Basement	
Public Public Basement	Pipes: ABS Plastic Cast Iron Copper Lead Galvanized Steel Brass Not Visible Pipes observed 69.50 Main waste line clean-outs were were not observed
Private Private	Pines observed by Co in Cl. + + + Cof
Location of wellhead	Main waste line clean-outswerewere not observed
4. 1	Cheater vent(s) noted
Main Shutoff valve: at entry	Venting was was not observed extending through roof
Supply Pipes: Copper Plastic Galvanized	and was was not seen in attic  'S' traps noted in drainage system, should be rectified'
Brass Lead Could not determine	
Conditions requiring attention:	No 'P' traps visible Conditions requiring attention: Ver + 5 +acks loos
	Leaks in waste system.
Dietribution Pines: Conner Plastic Galvanized	None notedactive leaksdry leak type stains
Distribution Pipes: Copper Plastic Galvanized Brass Lead Kitec Unknown metal Conditions requiring attention:	were observed
Conditions requiring attention: Jeose pining	Odour noted at, have evaluated by
	plumber
Leaks in water supply systemNone noted	Discharge Public Private
Rust / Corrosion noted	Reported byVendorRealtorNot Determined
	Drain line exits at
, Hose Bibs /	
NumberNoted	Wąstę Ejectors
When turned on water came out, when turned off the	None Noted
water did did not shut off fully.  When turned on water did not come out	Drain or waste ejector pumps were observed Location
Not tested, because	When water was run the pump(s)did did not
Interior: Hose bib shut off valve(s) located add new handle	
Hose bib shut off valve(s) located 428 hew hand	Change ejector pipe to PVC/ABS
Did not locate at, locate and leave accessible	Domestic Water Heater
Frost protected, interior shutoff may not be required	Location basement
	Rental Owned Sunknown
Functional Flow	Tetimeted and trans
TestedNot Tested because	Estimated age / year (2009) Make: John Wood
Method: With multiple fixtures running, flushed toilet(s)	✓ Gas Electric Oil Propane I
to over stress flow, observed decrease in flow:	Water on Demand system Integral with heating system
minimalacceptableexcessive	Water on Demand system Integral with heating system Rated Capacity gallons Liters, which is generally ample for about people, depending on usage.
Hot Water Output	ample for aboutpeople, depending on usage.  Safety pressure release valvewaswas not observed
Hot Water Output:  Hot water was not received at hot water faucets	anddiddid not have safety extension down to floor.
which were operated, in random testing, indicating the system	No Some Extensive rust / corrosion / water
is is not providing hot water to these faucets.	noted at base of unit indicates unit is leaking.
After about minutes of running hot water at sink faucet, water coming from faucet was	
sink faucet, water coming from faucet was	Vent Pipe:doesdoes not slope or rise to exhaust
hotwarmcold.	pipe looseconnection(s) loose rusted or deteriorated
	joint to exhaust in need of repair
	·
Additional Comments or Issues:	
	, and the second

Course of Action: Have a plumber or other appropriate contractor repair / replace items noted as needed.

# Heating

	General Heating System	Distribution
	Fuel;	Ductwork / RegistersUnobserved Radiant
	Gas Oil Electric Wood Propane	Baseboard heaters Thermostat(s)on unitson wall
Ì	'Type:	Radiators Bleed valves Leaks / Corrosion
İ	Forced AirElectric BaseboardElectric RadiantHot Water RadiantBoilerSteam BoilerGeothermal	Heat equal at both ends, indicates proper distribution within unit
	High efficiency mid-efficiency low efficiency	Boiler system: pressure release valve extension missing
	Integral with water heater / water on demand system	Heat supply & return PIPES:CopperGalvanized Iron PlasticUnknown material
ļ	Approximate age/year of system 22 as evidenced by:	Observed in: Spasement crawlspace affic
	Approximate age/year of system 22 as evidenced by:	Observed in:
	Brand Name: Keep Rifte  Furnace not operated due to temperature (see opposite page	Heat Distribution:
	Furnace not operated due to temperature (see opposite page	was was not found in each room – add as needed
Acres 1	for testing limitations)	Distribution missing from: <u>basement</u> areast
	Recommend Service Clean Furnace	Heat Recovery Ventilator (HRV) noted:working properly
	Remove filler pipes for previous heating system Improve clearance around furnace for safety and access	Recommend maintenanceRecommend service Course of Action:
	Previous oil tank notedOil line noted below surface,	Clean Ducts
	recommend further evaluation. Estimated age of oil tank	Insulation on heating pipes/vents, recommend test for asbestos
	Add vent to furnace room	Seal gaps/joints at ductwork and plenum to maximize the
/	Corrosion/rust/water noted in furnace, evaluate and repair	efficiency of distribution system.
4	Controls	
	Heating System was was not in use during inspection	Heat Evehancer
		Heat Exchanger  Heat exchanger is hidden from view, inside the unit, and therefore
	Thermostat(s) we're located main floor The system seems to be regulated by individual controls	cannot be inspected.
	in each heated areaon the heating units themselves	The following evidence suggests that the heat exchanger may
	When turned on by above thermostat(s)/control(s), units	be defective
ļ	fired or gave heatdid not fire or give heat.	
	HRV control (s) located in	Filters
	A furnace electrical disconnect notedabovethe unit	Air Filter in warm air heating/cooling unit.
	An automatic Shut-Off Safety Device(s) was noted	Washable Disposable Flectronic HEPA
	on the oil line attankburner	Location at furnace in return grill
		Not installed properly to correctly filter air
	Energy Supply	None noted, have it located and evaluated or have installed
ļ	Gas, believed to be publicElectricity	by heating contractor.
1	Oil tank in basementFill pipes indicate possible buried oil tank	Heating contractor should rectify defects.
	Gas, onsite, evidenced by white storage tank	Recommend non-allergy type filter
	Entry Location + rent  Gas meter location appears too close to vent/A/C, have checked	Filter appears clogged/blocked replace/clean
	by HVAC technician Bond gas line to proper ground	Oil Line Filter:
ı	Fuel Leaks noted? No Yes	Located near entry into basementnear oil tanknear furnace
ľ	Flue Pipes	Oil filters should be serviced by a heating contractor annually
	Flue pipes were identified	along with the oil heating unit.
	DoDo not rise slightly to chimney / exhaust	
	Joints appear loose Rusted or deteriorated	Humidifier None noted
	Connection to exhaust is loose or in need of repair	Location:return ductheating duct
	Pipes too close to combustibles, recommend repair	Filter appears clean Adjust water level
Ī	Supplemental Heat	WorkingNot workingDisconnected
	None noted Some noted	Parts Missinghumidifier should be replaced
1	Type, Location, and operation:	Drum type humidifier, recommend replace with drip type
		Humidistat Located:
L		
	Additional Comments or Issues:	
- 1		

Course of Action: Have a heating contractor rectify any defects noted above.

# **Basement & Crawl Space**

Basement  7 5 Percent of lowest levelFinishedPartially finished  Exterior access / egressNone notedDirect walk outUp exterior stairway bulkhead	Basement Ceilings  Exposed to view Hidden from view Partial view Ceilings finished? Yes No Evidence of Previous Active leak
Foundation walls:CoveredVisible Approximate percentage visible Limitations to a thorough inspection:StorageInsulationWalls finished / drywall / painted Visible areas:BlockConcreteBrick & MortarStone & MortarStucco over unknownCondition:Stucco over unknownSatisfactoryEvidence of previous wall repairEvidence ofPreviousActive leakSettlement cracksMinorMonitor over timeSignificant, have a mason repairHave cracks / leaky areas repaired to prevent ongoing leakage	None noted  Accessible Not Accessible Entered Not Entered, because Oww  Floors: concrete dirt Ventilation: noted none noted (add Ventilation) Type: wall vents vents into basement Recommend adding ventilation to this are to prevent condensation / moisture problems Additional ventilation recommended Evidence of moisture; determine source and repair as needed  Insulation observed: Yes No; Adequate? Yes No Vapour Barrier: on warm side of insulation
Basement Floors  Concrete dirt	None notedInstalled improperly  Moisture Evidence:PresentNot noted  Water Penetration Evidence:notednone noted
Covered withtile sheet goodscarpetingpainted	Slab on Grade  Not ApplicablePercent of lowest levelconcretewoodunknown / not visible slab:at about grade levelslightly above/below grade The support system below grade is not observed and is unknown. The exterior perimeter of the slab, where visible, crackswerewere not notedNo areas visible Exposed interior floor coverings are of:concretevinylwall to wall carpethardwoodsoftwoodcarpet less than wall to wall in coverage Observedbrokenwarpedrippledfloor coverings, which may indicate cracks in the slab.  Floor Drainage Floor Drainage Floor Drainage observed:YesNodiddid not have protective perforated cover Trap primer noted?YesNoEvidence of trap cracked / brokenRecommend install backflow preventer
Exterior Support Piers  Not Applicable Support columns ofMetalConcreteWoodStoneBlockBrick were observed under theSupport columns condition lookedSatisfactory	Cold Room  Not Applicable Install/replace weatherstripping at door Venting installed venting blocked, open and leave active No venting, proper venting to be added It is not recommended to finish or partially finish a cold room. Revert area to original state.
Additional Comments or Issues:	

Course of Action: Have a masonry or other appropriate contractor repair the above items as indicated.

## **Water Penetration & Internal Structure**

	Water Penetration	Foundation Structure
	No signs noted	Joists
	Evidence indicates a one time flooding	Not visible
	Some extensive evidence of ongoing water penetration	WoodSteel
	was observed	
	Evidence observed:	Conditiongooddefects noted, see below
Secretary .	Water stains on: On walls, at base of wall floors	Span and beams appear adequate
-	On walls,at base of wallfloors	Defects Observed:
	base of stairs around furnace	Cracks / cuts that reduce effectiveness, repair
$\bigcirc$	Efflorescence Rot	Joists span too large, add additional support
	Microbial growth / mildew	Rot on joists has reduced strength, repair
	Rust on nail heads/ baseboard heaters, etc.	Evidence of sagging floors that is,
l	Sump pump, see section	Minor / older, monitor over time for changes
	Wall board damaged	Movement appears to be recent and/ or ongoing, add
	Damp or wet floor coverings	additional supports
	Lifting tile	Add (#)joist hanger(s)
	Other	
		Columns
	Limitations to inspection:	Not visible
	Subfloor & carpetStorageFurniture	Wood steel poured concrete block / brick Appears to have been altered/removed have evaluated
İ		Appears to have been altered/removed have evaluated
	Course of Action:	Condition:
	Overall, stains indicate previous flooding	Columns appear sufficient and in good condition
·	Further evaluation necessary	Columns appear to have shifted, repair immediately
	Repair current leak issues noted	Defects observed: deteriorated and or
	Further evaluation and testing for possible mould recommended	Rot undersized (repair/replace)
-	(and remediation work performed as required)	Defects observed: deteriorated and on Rot under sized (repair/render)  Cracks have reduced strength, add additional support  Insect intestation appears to have compromised columns
	General Dampness	Insect infestation appears to have compromised columns,
ŀ		repair immediately
	None noted	
	Feels dampSmells damp	Sump Pump
	Dehumidifier noted	None noted
	Location:	Location:
	Dehumidifier was running during inspection	Location:pedestal
	Evidence that dehumidifier running continuously	Running continuously
	Recommend use of dehumidifier in basement	
		Activated Not working
ľ	Basement Ventilation	ActivatedNot workingCould not test unitNo water in the hole
	Eddonioni Fondiquon	Not plugged in (Electrical)
	None noted	Recommend backup system or alarm
	RONO HOLOG	Neconfine to backup system of alarm  Operating properly  Slow  Replace
I	Type:	Operating propertyOtomIzehiace
	Louvered wall vents	Discharge
	Window 5	Exterior Storm drain Unknown Sewer connection
	Area open to main and / or upper floors (open stairwell)	ONO CONTROL CONTR
	Exhaust fan	Course of Action:
	Air Exchanging unit	repair/replace
	Other	install sump pump
		Redirect discharge
	Course of Action:	install check valve
	Add additional ventilation to reduce condensation / moist air	
	Additional Comments or Issues:	

Course of Action: All defects noted above should be corrected and/or monitored by an appropriate contractor

## Laundry & Wet Bar

Laundry Area	Laundry Tub
No long day and 200 and 1	None noted
No laundry provisions noted	Tub
Location:BasementMain floorUpper floorIn/near bedroomsIn bathroomIn/near kitchen	Porcelain Steel Plastic Concrete
	Tub damaged / cracked, replace
Appliances: Laundry	
Clothes Washer CST2302573	Faucets:
	Faucets hot and cold working properlyFaucets do not shut off fully
Brand Kenmorie	Hot and cold reversed, have a plumber repair
Brand None noted Keyn more  Age: Newer Older Midlife	
Connections for water & drain were noted	Drain securenot secure
Connections not visible	No leaks noted
Condition of water hoses:SatisfactoryReplace	Leaks noted at faucetsbelow tub
	Leaks at water lines
Electrical OutletGroundedNot grounded Replace outlet	
In use during inspection, performing normal cycles	Wet Bar
Operated one cycle, heard water come in, splash, spin	None noted
and pump out	(—————————————————————————————————————
Not operated	Location:Wet barAdditional sink only
Course of Action:	Wet barAdditional sink only
Have an appliance repair contractor repair noted defects.	Other
Clothes Dryer MT3201540	Sink
None noted Kella Man 1973	Porcelain Steel Plastic Concrete
bianu - Crinisi e	Drainage pipes
ElectricGas	CopperPlasticCast IronLead
Connections were noted Not Secure	Galvanized Steel
Connections not visible	
Vented to:ExteriorNot vented properly, redirect  Age:NewerOlderMidlife	Leaks noted None noted
Total	Above the sinkbelow the sink At taps
Unit checked for spin and drying heat	
In use during inspection, performing major functions	Counter top
Not operated	Plastic LaminateCeramic TileWood
Course of Action:	areare not secure loose (unsafe)missinglarge areas heat
Change dryer vent to metal	scorched or damaged
Vent appears clogged / dirty, requires cleaning (All dryer vents.	Stored items affecting visibility of counter tops at time of
require regular maintenance, see preventative maintenance booklet for more	inspectionminimalabout normalextensive
information	
Have an appliance repair contractor repair noted defects.	
Electrical: Laundry	Electrical: Wet Bar
Ground Fault Interrupter X None Noted	Ground Fault Interrupter None Noted
Ground Fault InterrupterNone NotedRecommend add GFI's for safety	Recommend add GFI's for safety
Additional Comments or Issues:	

Course of Action: Have an appliance, plumber or other appropriate contractor evaluate and repair as needed.

Page 26 of 38

## Kitchen & Appliances

Location	Range/ Cooktop AI/A
Basement Main floor Upper floor	Brand: Jehh Acc
opportion	Style: Free Standing Built in
Ochlingto	Style. Place Stantaing Built in
Cabinets	Fuel type:Electric GasOther
WoodenPlastic LaminateOther	Age:OlderMidlife
Cabinets are are not secure end of life	Not operated
Doors and drawers: function as expected loose cabinet	In use during inspection, indicating portion being used is
missing hardwaremissing door or drawer fronts	performing its major function
broken drawerswarped doorsadjust doors	4 Operated and found that # 4 burners gave heat and
Stored items affecting visibility as to condition at time of inspection	#did not give heat
were:MinimalNormalExtensive	
	Oven
Counter Tops	Brand:
Plastic Laminate Ceramic Tile Granite/Marble/Corian	Part of the stove Built in
areare not secureloose (unsafe)missing	Fuel Type:Electric GasSelf cleaning(Not checked)
large areas heat scorched or damaged	Age:NewerOlderMidlifeSee Stove
Stored items affecting visibility of counter tops at time of	Not operated,
inspectionminimalabout normalextensive	In use during inspection, indicating the portion being used is
	performing its major function
Sink	portorning to major remotion
Stainless SteelPorcelainPlastic	Bake and broildiddid not give heat when turned on.
Undetermined material	uid fiot give fleat when turned on.
Ran the water and found leaks None notedAbove the sink	Pofrigorator OAA 52 (
below the sink. Have leaks repaired by plumber	Proud: 701 1 A So
	Brand: Newer Older Midlife
Sink chipped/cracked. Stopper/strainerwaswas not noted	
	In use during inspectionOperated
Disposal	Not operated
None noted	Items in cooling section felt cool, in freezer section felt frozen
Brand horsepower_	-indicates doing major functions
Leaks noted?YesNoHave leaks repaired by plumber	Features: Vater & Ice through door Frost Free
Tested unit, results:	Magnetic Seal:Damaged / Broken / Tco maker
Ventilation	Features: Ice maker Water & Ice through door Frost Free Magnetic Seal: Damaged / Broken Ice maker Brand: Dishwasher FL 503604
None Noted, other than doors and windows	Brand: Kitchen Acc
Fan integral with a built-in Microwave or cooktop	Age: Newer Older Midlife
Exhaust fan appears to vent to exterior	
Recirculates air within the room Light	Not operated items/storage in machine
When the components were turned on, they seemed to	HeardDid not hear water come in, splash and pump
perform their major function.	out, indicating that the appliance is doing its major functions
Fan sounds excessively noisy	Recommend relocate drain to sink side of P trap
Filters: Observed None Noted	Recommend secure unit
	Built in Microwave
Electrical	None noted
Ground Fault Interrupter None Noted	Brand.
Recommend add GFI's for safety at sink left	Age:NewerOlderMidlife
Inadequate number of electrical outlets	Heated container of water, indicating does major function
	Too close to cooktop, repair as needed
Kitchen Floor	Not operated,
LaminateVinyl TileCeramic Tile	Other Appliance
Wood Carnet	None noted
WoodCarpetexcessive bounce noted	
Have a flooring contractor correct any defects or	Brand:OperatedNot Operated
<u> </u>	Operated INDLOPERATED
deficiencies noted in floor.	

Course of Action: Have an appliance repair or other appropriate contractor repair any deficiencies noted above.

#### **Bathrooms**

RATHROOM 1: Full Partial	RATHROOM 2: Full Partial
BATHROOM 1: Full Partial Location Main Hoor	BATHROOM 2: Full Partial Location Partial When I Leg Tub None noted
Tub:Built inLeg Tub _>_None noted	Tuh: Duilt in Log Tuh Mono noted
Shower:with TubStall	Shower:Swith Tub Stall
Snowerwill rubStall	
Enclosure:PlasticCeramic	Enclosure: Plastic Ceramic
Seems adequately fastened to wallYes No	Seems adequately fastened to wall Yes No
Missing/damaged groutEvidence of moisture behind tiles	Missing/damaged groutEvidence of moisture behind tiles
Sink(s): # Vanity Wall Hung Pedestal	Sink(s): #/ Vanity Wall HungPedestal Feels adequately fastened Yes No
Feels adequately fastenedYesNo	Feels adequately fastened Yes No
Toilet: Flushed, Feels adequately secured YesNo	Toilet: Flushed, Feels adequately securedYesNo
Bidet: None notedTurned on	Bidet: None notedTurned on
Feels adequately fastenedYesNo	Feels adequately fastenedYesNo
Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps	Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidet Taps
Noted at Tub Shower Sink Bidet Taps	Noted atTubShowerSinkBidet Taps
Floor:Vinyl Ceramic Tile	Floor: Vinyl Ceramic Tile
Soft or weak spots noted in floor	Soft or weak spots noted in floor
Vents: Window Exhaust Fan None noted	Vents: Window Exhaust Fan None noted
Caulking: Around tub/shower at walls and floor is	Caulking: Around tub/shower at walls and floor is
Loose Mildewed Missing Re-caulk as required	Loose Mildewed MissingRe-caulk as required
Leaks: None noted	Leaks: None noted
Noted at TubShowerSinkBidet	Noted at TubShowerSinkBidet
From fixture From faucets	From fixtureFrom faucets
Electrical: Ground Fault Interrupter Install GFI	Electrical: Ground Fault Interrupter Install GFI
No receptacles	No receptacles
140 1000 ptables	No locopidolos
Plumbing noted on exterior wall, unacceptable	Plumbing noted on exterior wall, unacceptable
i lumbing noted on exterior wall, unacceptable	Iditibility noted on extends wall, unacceptable
RATHPOOM 2: Full Partial	RATHROOM A: Full Partial
BATHROOM 3: Full Partial Location	BATHROOM 4: Full Partial Location
Tub:Built inLeg TubNone noted	Tub:Built inLeg TubNone noted
Shower:with TubStall	Shower:with TubStall Enclosure:PlasticCeramic
Enclosure: Plastic Ceramic	
Seems adequately fastened to wallYes No	Seems adequately fastened to wallYes No
Missing/damaged grout Evidence of moisture behind tiles	Missing/damaged groutEvidence of moisture behind tiles
Sink(s): # VanityWall HungPedestal	Sink(s): # VanityWall HungPedestal
Feels adequately fastenedYesNo	Feels adequately fastenedYesNo
Toilet:Flushed, Feels adequately securedYesNo	Toilet:Flushed, Feels adequately securedYesNo
Bidet:None notedTurned on	Bidet:None notedTurned on
Feels adequately fastenedYesNo	Feels adequately fastenedYesNo
Damage:None NotedCracked / Chipped	Damage:None NotedCracked / Chipped
Noted at TubShowerSinkBidet Taps	Noted at TubShowerSinkBidet Taps
Floor:VinylCeramic Tile	Floor:VinylCeramic Tile
Soft or weak spots noted in floor	Soft or weak spots noted in floor
Vents:WindowExhaust FanNone noted	Marster Minday, Cybeyd Con None neted
Caulking: Around tub/shower at walls and floor is	vents:vvindowExhaust rannone noted
Loose Mildewed Missing Re-caulk as required	Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is
Loose Mildewed Missing Re-caulk as reduited	Caulking: Around tub/shower at walls and floor is
	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required
Leaks: None noted	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks:None noted
Leaks:None notedSinkBidet	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet
Leaks:None noted Noted atTubShowerSinkBidetFrom fixtureFrom faucets	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks: None noted Noted at Tub Shower Sink Bidet From fixture From faucets
Leaks:None noted Noted at TubShowerSinkBidetFrom fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks:None noted Noted at TubShowerSinkBidetFrom fixtureFrom faucets Electrical: Ground Fault Interrupter Install GFI
Leaks:None noted Noted atTubShowerSinkBidetFrom fixtureFrom faucets	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks: None noted Noted at Tub Shower Sink Bidet From fixture From faucets
Leaks:None noted  Noted atTubShowerSinkBidetFrom fixtureFrom faucets  Electrical:Ground Fault InterrupterInstall GFINo receptacles	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks:None noted Noted at TubShowerSinkBidetFrom fixtureFrom faucets Electrical: Ground Fault Interrupter Install GFINo receptacles
Leaks:None noted Noted at TubShowerSinkBidetFrom fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	Caulking: Around tub/shower at walls and floor isLoose Mildewed MissingRe-caulk as required Leaks:None noted Noted at TubShowerSinkBidetFrom fixtureFrom faucets Electrical: Ground Fault Interrupter Install GFI

Have all above items corrected by a plumber or other appropriate contractor before items deteriorate further.

## Fireplaces & Common Safety Devices

Fireplace # 1	Ground Fault Interrupter (GFI) Protection
None noted	No GFIs noted in house wiringGFI(s) noted in panel box
Location	GFIs noted in branch outlets GFI(s) noted on exterior
MasonryMetal prefabricatedWood Stove Insert	· · ·
Gas Insert Working  Firebox: Metal Masonry	Testing & Results:
Firebox:MetalMasonry	using an electric tester plugged into outlet
Firebrickloose mortar	using test button on GFI. All devices testedDIDDID_NOT trip, as expected.
Abnormal openings (Cracks, missing grout, etc.)	All devices testedDIDDID NOT trip, as expected.
Flue:Dirtysharedmissing linerClearance	(exterior side)
Damper:Opened and closedCould not open & close safely	Course of Action:
Broken or missing parts	GFIs should be retested & repaired/replaced by electrician and
diddid not observe flue liner	more added, as needed.
Combustion air supply:InteriorExterior air	GFIs should be installed Kitchen
Limitations:Fire burning area blocked, unable to inspect	GFIs are older, recommend replacement
Pilot light was off during inspection	Smoke Detectors
Course of Action:	·
Have WETT Certified contractor clean, test, evaluate and	None Noted, have an electrician install immediately
certify before use	#Smoke Detectors
Have fireplaces cleaned annually by a chimney sweep	
	X_Not Tested as may be connected to wired / wireless
Fireplace # 2	alarm system in house, they should be tested by alarm company
None noted	before sleeping in house.
Location	
MasonryMetal prefabricatedWood Stove Insert	Course of Action:
Gas Insert Working Firebox: Metal Masonry	Install additional smoke detectors
	upper floor main floor Basement
Firebrickloose mortar	Within 5 feet of bedroom doors
Abnormal openings (Cracks, missing grout, etc.)	Replace smoke detectors
Flue:Dirtysharedmissing linerClearance	Relocate smoke detectors
Damper:Opened and closedCould not open & close safely	
Broken or missing parts	X Test smoke detectors monthly
diddid not observe flue liner	X_Test smoke detectors before sleeping in the house
Combustion air supply:InteriorExterior air	
Limitations:	Carbon Monoxide (CO) Detectors
Fire burning area blocked, unable to inspect	
Pilot light was off during inspection	No permanently installed CO detectors noted
Course of Action:	#CO Detectors
Have WETT Certified contractor clean, test, evaluate and	
certify before use	X Not Tested as may be connected to wired / wireless
Have fireplaces cleaned annually by a chimney sweep	alarm system in house, they should be tested by alarm company
	before sleeping in house.
, Wood Stove	Install CO detector in hall on all sleeping levels at knee level
None noted	Replace Carbon Monoxide detectors
Location	X Test CO detectors before sleeping in the house
Fire burning at time of inspection, unable to inspect	
Have WETT Certified contractor clean, test and evaluate	Interior Fire Sprinkler System
Have clearances of wood stove and flue pipes evaluated by a	None Noted
WETT Certified Contractor	Noted, have evaluated for proper operation
Have WETT Certified contractor evaluate condition and	Sprinklers are not tested, because to do so would cause flooding and damage to
clearances of wood stove and flue pipes	furnishings in the home. Have system evaluated by an appropriate contractor.
Additional Comments or Issues:	

Course of Action: Have an electrician install safety devices before sleeping in the home

## **General Interior**

ſ	Ceilings	Doors
	DrywallWoodMetalAcoustic ceiling tiles Plaster overWood lathMetal meshwall board Unknown backer material Appears recently painted / paperedNail pops were notedNo major defects were notedWater stains inarea	Mainly door types of:Hollow coreWoodPlastic Hinged one sideBi-foldLouveredMirroredSliders  Defects noted:Some adjustments could be made to the door fitDoors do not open and close easily
	Appears dry, monitor over time The following major defects were noted: cracks + unfinished areas	Doors or hinges feel/look looseDoors with holes & broken partsDoors missing from opening which normally would be
	Walls  Drywall Wood Panel covered  Plaster over: Wood lathMetal meshwall board	expected to have doorsDoors with missing, broken or damaged hardware / locks
	Unknown backer materialUnknown materials No major defects were noted Appears recently painted / paperedNail pops were noted  The following major defects were noted:	Windows Primarily the following types of windows were observed: Single hung Double hung Casement Sliding Awning Hopper Fixed panes
l	Floors  Wall to wall carpet Room sized rugs Hardwood Laminated Wood Plywood Sheet goods  Vinyl tiles ceramic tile  When bounced on, a normal amount of bounce was noted excessive bounce was noted  Slanted floors noted on main upper floor, monitor for ongoing movement	SomeMost seem to have insulated glazing (glass) They appear to be made of:WoodMetalPlasticA combination of materialsUnknown  Random tested windows and found Window SashDoDo not open or close under normal pressure
	Trim None noted (base of walls, around doors & windows) Mainly, material type of:WoodPlastic Trim isPaintedStainedUnfinishedPaint or finish was observed to be peeling. Trim was observed to beloosemissing insomea fewmost places  Stairs, Balconies, & Railings	Defects: Broken glassBroken, rotted or loose sash piecesBroken or defective counter balance devicesMissing handles, locks, and hardwareMissing screensDamaged screens, replaceStains, indicating leaks or condensationFogged up / Condensation notedbroken thermal sealsRecommend replace windows for energy conservation
	To BasementTo AtticBetween living levelsFelt solid under foot, rise and run felt about even	
	Trip hazards observed: Uneven rise and run from step to step Weak or springy treads or stringers Loose treads	Skylights and Roof Windows  None noted from interior Appear fixed did not operate Results:
	Loose handrails noted on 2 tho stairs  Loose carpet or tread coverings  arge openings in rail system should be closed down  Steep steps (rise too high)  No handrails noted on Basement stairs  Course of Action: Stairs  Add handrail for safety  Railings too low by today's standards, add / adjust for safety	SomeMost seem to have insulated glazing (glass)  Leaks (around unit):None noted Small stains noted Excessive staining/damage noted  Condensation/Leaks (abutting glass)None noted Small stains notedExcessive stains noted Active water penetration observed
	Additional Comments or Issues:	<u></u>

Course of Action: Have a carpenter or home improvement contractor correct defects noted above

## Insulation

A 11	
Attic	Ductwork
None notedAttic could not be accessed	None noted
Fully flooredSome observed, mostly obscured	CSomemost ductwork in unconditioned spaces
Form:	was observed to be insulated.
Batt / BlanketLoose FillRigid Board	Insulation appears to beadequateinsufficient
Foamed in Place	Observed:CondensationRust
Type:	Uninsulated ducts should be insulated for energy conservation and to
Glass FiberWood ShavingsMineral Fiber	prevent condensation and resultant damage.
Cellulose FiberUrea Formaldehyde Foam (UFFI)	<b>,</b>
Plastic/Foam BoardVermiculite, test for Asbestos content	Dinoc
	Pipes
Other	None notedHeating cables
Location:	Somemany pipes believed to be carrying heated
Floor Roof Both other	or chilled water or coolants in unconditioned spaces were
	observed to be insulated.
Estimated thicknessUnknown	Insulation appears to be adequateinsufficient
,	Uninsulated pipes should be insulated for energy conservation and to
Estimated R-valueR	prevent condensation and resultant damage.
Defects:	
Wet Compressed Mildew / fungus	. Walls
Evidence of past or current rodent infestation	<b>27.1</b> • • • • • • • • • • • • • • • • • • •
Insulation appears, smells or feels damp/wet, replacing	Through hole in wall/legated
	Through hole in wall(located, type of insulation.
should improve efficiency & reduce allergies.	type of insulation.
Low / bare spots in insulation, recommend additional insulation	Domoved # outerior well outlet covers on interior
Vapour barrier: None Noted Not visible	Removed #exterior wall outlet covers on interior
Plastic Kraft Paper Polyethylene Other Not determined Barrier is located on warm side of the insulation	of house and saw
Other Not determined	While the above does not determine that the walls are or are not insulated,
	it may give an indication of what is in the walls. Sometimes insulation
Barrier is within insulation or on cold side, have repaired	is placed behind electrical boxes and nowhere else.
Exhaust pipes from interior:	
Adequate insulationwetcondensation	Building Underside
Clearances	Not Applicable
Adequate around pot lights, fans other mechanical items	None noted
Electrical wiring observed within or on top of insulation, have	From within a crawl space / basement, under floor of the
secured.	lowest living areainsulation was observed.
Course of Action:	And the state of t
Adding additional insulation should be considered to	Estimated thickness inches thick
increase energy efficiency of home.	Estimated R-value ofR.
morease energy entolerary of northe.	Louisiand IV value of
Additional Comments or Issues:	
Additional comments of issues.	
Course of Action: Have an appropriate contr.	actor replace or add insulation where needed.
Course of Auton. Have an appropriate contact	notor replace of and mediation micro needs.
•	* *4 4*
	imitations
Normal furnishings and floor, ceiling, and wall coverings will obstruct the	ne view of the inspector. In addition to the standard obstructions, the
following items further limited the inspection:	
Exterior	Interior
plantings too close to building	Furnishings throughout the house
snow and ice buildupvines on the building	normalminimal,excessive
debris, leaves, brush, wood or other items piled against	Stored items:
	throughout the house,basement,attic
exterior of building	
Other	normalminimal,excessive
Exterior appears recently painted/sided	Interior appears recently painted/papered
	Renovation work recently done
These items may have prevented the inspector from seeing some item	
Once these conditions change or are changed defects or deficiencies	may be found