### Lighthouse Home Inspection Report

The main purpose of the Lighthouse home inspection is to provide clients with a better understanding as to the general condition of the home. A visual inspection of the building and its immediate grounds has been conducted in accordance with the pre-inspection agreement and the standards of practice in the home inspection industry. The facing pages outline general information and the Lighthouse standard of practice. This information forms an integral component of the inspection results and should be reviewed thoroughly in conjunction with the personalized sections of the report. The home inspection report is confidential and was prepared for the exclusive use of the client as identified in the agreement.

	Sum	nmary	
Address of Inspection:/3 /3	undas	St. E. Toron	to
Date of Inspection: Nov. 22/16	Approximate s	start time:A.M. P.M. (circle) stop time	45 A.M. P.M.
Recent WEATHER conditions:	windy	Rain past 3 days: XYes	LightNo
Weather at start of inspection:over	:95+1	Rain past 3 days: Yes Ground Condition Wet	Snow
Approximate outside temperature during the inspe			
Front of Building facing:NorthSouth	EastWest	t In Attendance:ClientHomeownerC	Other
General Accessibility:Excessive storage			
Utilities turned offOccupied room of	or section	Access deniedOther	
Refere	ence: Item	& Page Number	
		1-	
General Structure & Roofing	4	Basement & Crawl Space	22
Chimneys & Roof Drainage	6	Water Penetration & Internal Structure	24
Vehicle Parking	8	Laundry & Wet Bar	26
Exterior	10	Kitchen and Appliances	28
Additions	12	Bathrooms	30
Grounds & Air Conditioning	14	Fireplaces & Common Safety Devices	32
Electrical	16	General Interior	34
Plumbing	18	Attic & Ventilation	36
Heating	20	Insulation	38

pose immediate safety hazards may be observed and omitted from this page.

The overall, general habitability of this home, taking into account the entire report, is in the opinion of the inspector:

Great home, excellent shape. Some typical minor issues noted.

If you have any questions, we encourage you to contact your inspector at

Page 2 of 38

Copyright @ 2015 Lighthouse Inspections

### **General Structure & Roofing**

Building Style	Roofing
Detached	Roof Style(s) Gable Shed Hip Flat
Semi- Detached	MansardGambrelRidgePitched
Townhouse	
Condominium / Apartment	Roof Covering(s)Asphalt ShinglesTar & Gravel Wood ShinglesMetalRolledSlate / Clay Tiles
Bungalow	Rubberized Membrane
2 Storey Split Level	Estimated life span: Younger Mid-life
	Older or End of worful life
2nd floor extends out beyond 1st floor	Older or End of useful life Number of layers 3 / 99ble roof
Estimated Age:Under 10 years10-2525-6060+over 70 years	Inspection Method:From ground with binoculars from a window from roof edge
Occupancy: Occupied Vacant Staged	Identified the following conditions:
General Construction:	lifting / clawing / cupping / curlingbubblingdirty
Wood FrameMasonry	
Florida	excessive moss of mold growing of foolwaves and dips noted between structural members, see ATTIC
Flashing	
Material None noted unknown metal Rubberized membrane Galvanized	section of report
Material not determined	Valuator roof covering indicators:
Defects: Appears to be patched	Younger roof covering indicators:laying smooth
	cleannestrootouraying smooti
From interior, stains or wet spots indicate possible	Inspection Limitations:
leaking at or near flashing	Theportion of roof was not visible to the inspector
Limitations:% not visible	and should be inspected by a roofing contractor to determine condition
	and one of the control of the contro
Course of Action:	Roofing is mostly snow covered
<u></u>	Flat roof is covered by decking and could not be inspected
	Leaks see Moisture and water penetration in ATTIC section of report.
Skylights & Roof Windows	
None noted on exterior of house	Course of Action
# of units noted	Recommend roofing contractor reroof
Type:DomedFlushRoof Curb identified	Recommend roofer
Material:glassplasticunknown material	
Patching noted around unit on roof	Soffit & Fascia
Evidence of condensation noted	Soffit: aluminum wood plastic
Caulking around unit: appears adequate	Painted Paint deteriorated Mould
missing or damaged, recommend repair	Rotted loose evidence of leaks rust corrosion
Defects noted: Cracked	Fascia; aluminum wood plastic
Glazing:double or triplesingle, requires repair	Painted Paint deteriorated Mould
Skylights and Roof Windows are also identified on Interior section	Rotted loose evidence of leaks rust corrosion
of report.	
Additional Comments or Issues:	Tseal at front root line
Additional Comments of Issues.	between gutter + shingles
	FIXED

Course of Action: Have a roofing or other appropriate contractor repair any deficiencies noted above.

## Chimneys & Roof Drainage

Chimney	Drainage
Brick Block Stone Metal	Nothing noted to direct roof run off
Chimney is covered, limiting inspection	On roof diverters were noted
Clearance sufficient above roof	
Decommissioned chimney; non-standard, have removed/sealed	
Chimney saddle on roof above chimney	Gutters and Downspouts
Number of chimney(s)	
High Efficiency exhaust	Material:AluminumCopperPlasticOther metal
Missing or loose mortarCracks	D. C. C.
Flue linerobservedcrackedmissing	Defects: Loose Broken Out of adjustment
Clean-out: located	Remove debris which is sticking out of system
operableUnable to operate, have repaired	Stains over outer gutter edge indicate overflow, system may be
Clean-outDirtyDamagedBlocked	clogged or undersized
Chimney cap / washobservedBroken / damaged	Leaking observed at:
Cap overhanging to protect brickNone noted	DrainsDownspoutsCorners of gutters
Rain Cap / Spark ArresterNone noted	
	Discharge:
Defects Observed:	Discharges onto ground
CrackedLooseDamaged	Discharge extended 6 feet from foundation
Deterioratednot visible	Discharges into pipe or hole in ground
Flashing at chimney secure	Did Did not determine where pipe exits
LooseDamaged, repair / reseal / replace	Recommend change to ground discharge
BEFORE USE, have chimney sweep clean, further evaluate &	Sufficient number of downspouts
repair as needed.	Add downspout at:FrontRearLeftRight side
Temporary / non-standard repair observed, recommend	Downspouts blocked
mason evaluate and repair as needed.	Gutters:
Course of Action:	RustyHolding water (adjust)
ourse of Housens	Clean gutters
Exterior Ventilation	
<b>89</b>	
Types:Gable End VentsRidge VentSoffit Vent	Course of Action:
WindowsAttic fan(s)Roof ventsTurbines	Recommend add / adjust splash blocksRecommend add extensions to downspouts to direct water
Self opening & closing louvered vents.	farther away from foundation
Side Walls:	Recommend redirect water discharge off lower roof – connect
No evidence noted to indicate need to increase ventilation	with lower gutters or direct to ground discharge
Spalling brick Mould/mildew spores	
Peeling or stained paint on exterior siding seems to indicate more	Downspout missing, re-install
ventilation is needed in side walls for the house to breathe better	Water penetration noted, make appropriate repairs
	Have the appropriate type of contractor make repairs as needed
Course of Action:	to the above components
Recommend adding ventilation	
Additional Comments or Issues:	

Course of Action: Have a roofing, masonry, or other appropriate contractor evaluate and repair as needed.

### Vehicle Parking

Driveway	Garage
None notedAsphaltConcreteStone or gravelInterlock	None Noted
III(ellock	Estimated Size:Car(s)
Defects noted:	Bays are: side by side tandem
Depressions or holes pose a trip or safety hazard and should	Attachedliving space above
be corrected.	Semi-detached Detached
Slope to building directing water to building or into garage,	Semi-detachedDetached Interior accessed:YesNo because
should be corrected.	Visibility limited by:Parked carStorage
Trench drain should be added across width of garage	
Crumbled/damaged surface may indicate water damage from	Floor:ConcreteAsphaltDirt
under driveway surface.	normal condition
	Defects:CracksDepressionsOil stained
Course of Action:	Deteriorated surfaces
	Walls:MasonryWood framed
	Framingexposed to viewblocked by storage / walls finished
Other Parking Area	Exterior finishes deteriorated, replace
None notedNot determinedOn street	Automobile doors:Overhead Swinging
Off street Common parking area	Number:such doors
	OperatedNot-operated, because
Carport	Electric opener noted
None Noted	operated not operated, because
Trong residu	Applied resistance and doordiddid not stop or
Size:Car(s)	reverse, as expectedAdjust sensor
Attached Semi-detached Detached	Missing safety cables inside of overhead garage doors
Visibility clear	springs, have contractor install.
Visibility obstructed by:Parked carStorage	
	Man doors:into houseto exterior
Floor:ConcreteAsphaltDirt	#doorsoperated
Normal condition	Replace weather seal Requires proper step(s)  Self Closing door? Yes No Add
Defects:Oil Stained Deteriorate surfaces	Not operated, becauseAdd
Deteriorate surfaces	Results:
Walls:Vertical supports onlyOpen to weather	Troduct.
Enclosed on #sides	Windows:Nonefixedoperational
	Not tested, because
Roof underside:Framing and sheathing exposed to view	Results:
from insideStored items restrict viewing	
	Roof underside:Framing and sheathing exposed to view
Water Penetration:Water stains	from insideDrywallStored items restrict viewing
Water leaking throughDamaged members	Freigned ettics Agests No second
Attice England attice Access No conces	Enclosed attic:AccessNo access
Attic:Enclosed attic:AccessNo access EnteredYesNo	EnteredYes No
Littered1es140	Water Penetration:Water stains noted
	Water leaking throughDamaged members
Course of Action:	
	Gas-Proofing: Seal any openings in the finishing materials to
	minimize the potential for gas entry into the home
Additional Comments or Issues:	
The second of th	

Course of Action: Have a home improvement or other appropriate contractor evaluate and repair as needed.

### Exterior

Wall Finishes	Foundation Walls
Location:AllMain FloorUpper floor	Poured Concrete Block & Mortar Stone & Mortar
Front Rear Side	Brick & Mortar Wood Stucco over unknown
Brick / MasonryWoodAluminum/VinylStucco	
Cement boardEIFS (Exterior Insulation and Finish System)	Defects:
Evidence of Condensation presentYesNo	Cracks observed were smaller, monitor over time
General ConditionTypicaldeteriorated	Larger cracks were observed, recommend repair
Repairs RequiredUpper floorUpper floor	Vines, shrubs, trees or other planting obscuring the view
Front Rear Side (Insulbrick)	of the foundation. These plantings will restrict the inspection
Rrick / MasonryWoodAluminum/VinylStucco	scope and may be hiding significant defects.
Cement boardEIFS	
Evidence of Condensation presentYesNo	
General ConditionTypicaldeteriorated	Structural
	No major structural defect evidence was noted, appears in
Repairs Required	/ <del>_</del> _ ·
	normal condition for its age
Finish too close to grade, repair	Major structural defect evidence was noted, as described:
Vines, shrubs, trees or other planting obscuring the view	
of the wall finish. These plantings will restrict the inspection	Course of Action:
scope and may be hiding significant defects.	
• • • • • • • • • • • • • • • • • • • •	Doors
Windows	SolidHollow coreFrench doorsSliding glass
Normal condition for age of houseUpgraded	Metal Wood fiberglass / composite
StormsScreensSome may be missing	Open & close as expected
Loose or missing glazing should be replaced	
Loose or missing caulk, have recaulked	Need adjustments to operate as expected
Trim, Observed:MouldDecay / rot	Broken door or parts need repairing/replacing
Re-seal sills	Missing/broken hardware to be installed/replaced/repaired.
Maintenance / repairs required at window frames	Reseal frames
	Storm doors Operated:open & close as expected
Basement window(s):	Doors require adjustment to operate as expected
None noted Wood Metal Plastic	Trim, Observed:MouldDecay / rot
Sash are located high near ceiling	
and openinoutslide sideways	Wood to Soil Contact
	was was not observed
Malle	
Window Wells	Location: rear yard (gates under
None noted	Location porch/addition
MetalWoodConcrete	Course of Action:
	Course of Action.
UncoveredCovered	Remove all decayed wood and raise any wood structure onto
Defects:BrokenCrackedCrumbling	concrete pavers as possible
Flooded Damaged cover	
Water Stains inside windows indicating poor drainage	Storage
Course of Action: Recommend adding well for drainage	Excessive storage at side of building, have removed
Cover should be installed/repaired to keep water out.	Wood piles against building, have removed, may provide
Close down openings for safetyRe-secure to wall	home to animals and insects.
Grade in well too high, lower	
Additional Comments or Issues:	

Course of Action: Have an engineer, Pest Control or other appropriate contractor rectify any deficiencies noted above

#### **Additions**

Main Entry	Deck and Balcony
Location: tront	None noted
ConcretePorch ofwoodconcrete	Location: rear yard
stone with stepswalls enclose area	WoodMetalConcrete
Deteriorated/damaged steps / supports pose safety hazard	. 22
#steps down from porch	# 22 Steps to grade
Step rise(s) too high / uneven, adjust	Too close to grade to look under
	Close to grade could only see under some sections
Handrails/guardrails:	Sufficiently above grade to get under and look
None notedRecommend add for safety	No access below: Blocked byStored items
Loose or unsafe, recommend repair for safety	Plant growth Elements(Snow, ice, water)
Railings too low by today's standards, add / adjust for safety	Defects: resecure top of stair
Walkways	No bolts noted to attach to house Bolt to framing
None noted	Install missing / additional joist supports
	Support columns not attached to foundation
To Main entry:ConcreteAsphaltPavers	Take steps to reduce sway or deflection noted
Slate Gravel Interlock / brick	Wooden piles / supports below soil, raise above soil level
Uneven/broken surfaces pose trip hazard	Wood flooring and/or structure deteriorated
	Improve supports as required / Fence a
Other walks:ConcreteAsphaltPavers	(no rail
Slate Gravel Interlock / brick	Handrails/guardrails:
Uneven/broken surfaces pose trip hazard	None notedRecommend add for safety
	Feel loose BrokenClose down openings for safety
Secondary Entry	Railings too low by today's standards, add / adjust for safety
None noted	(Some Spots not all)
Location: rear yard	Patio
Concrete slab Porch of wood concrete	None noted
stone with stepswalls enclose area	7
Deteriorated/damaged steps / supports pose safety hazard	Location:
# 5 steps down from porch	ConcretePaversSlateStoneInterlock
Step rise(s) too high / uneven, adjust	Uneven/broken surfaces noted which pose trip hazard
Exterior below grade entry notedrequires proper step(s)	
Requires proper drain	
Handrails/guardrails:	Retaining Walls
None noted Recommend add for safety	None noted / decorative only
Loose or unsafe, recommend repair for safety	Wooden:Pressure treated
Railings too low by today's standards, add / adjust for safety	Unknown if pressure treated Appear untreated
Railings too low by today's standards, add / adjust for safety	ConcreteBlockStoneBrick
Fauces	Mortar joints observed
Fences	
X	Drainage holes to relieve water pressure from behind the wall
WoodMetalOther	areare not evident.
secure	Defeater
looseweakBroken sections	Defects:   Buckling Bowing Cracking Leaning
Yard not fully fenced	Differential displacement Other displacement
Gate:operatedself-closerinstall self-closer X Inspector does not know ownership	Dillerential displacementOther displacement
X Inspector does not know ownership	
Additional Comments or Issues:	
Additional Commonts of Idonos.	

Course of Action: Have the above noted deficiencies corrected by the appropriate contractor

### **Grounds & Air Conditioning**

Grading	Air Conditioning
Within 6 feet of foundation:	None Noted
Front of house, slopes	
towardaway from houseis relatively level,	Location: rear yard
Right of house, slopes	44/1
towardaway from houseis relatively level	Brand name on central unit:
Left of house, slopes	
towardaway from houseis relatively level	Type:Central AirHeat PumpGas ChillerEvaporative CoolerElectric Compressor
Rear of house, slopes	Evaporative CoolerElectric Compressor
towardaway from houseis relatively level.	Roof or attic mounted (or other) system
Beyond 6 feet:	Ductless Air Conditioning system
Entire lot is relatively level	Water cooling system, recommend replace
Slopes away from house, acceptable	The state of the s
Slopes towards the house, should be graded away	and of the same
X Recommend grading slope to direct water a minimum of 6 feet	In use during inspectionOperated
from foundation to minimize water penetration	
General grading should be addressed as larger depressions	Not operated
can pose a trip hazard	(see opposite page for testing limitations)
Ravine lot, potential erosion concerns	
Recommend the following negative effect on the building is	
addressed:	
	Visible portion of equipment appears to be
General grading could not be assessed due to snow.	NewerMidlifeOlder
The state of the s	or ApproximatelyYears old
Trees, Shrubs, & Plantings	The state of the s
Trees, shrubs and other plantings near the home should allow the	Central unit appearslevelnot level
home to breathe	Outdoor fan is:obstructed
None noted near house which appear to pose a possible	Outdoor grills are:damageddirty
hazard to the house at the present time.	Have all debris removed before use
Planting(s) noted overhanging / touching /near to / climbing on	Compressor isnoisy
house	
These conditions should be corrected, usually involving cutting back,	Ductwork
pruning or removal of the planting.	in common with heatingindependent from heating.
Other plantings, away from house, should be inspected by	
client and attended to as needed	
onone and accorded to the mean	With unit running, house seemed to cool
Environmental	slowlyquicklyadequately not at all
Although not required as part of a Home Inspection, some evidence	
noticed by an inspector, which might indicate some environmental	Course of Action: rein sulate piping
hazard, chemical or oil spills:	
Dead foliage, out of season - looks unusual	
Dark stains on soilOil slick or stain on water	Individual room units observed
Abandonedmotor vehicle(s)batteriesPaint cans	operatednot operated
Pipes into the ground may indicate buried storage tanks	Results: received coolingdid not receive cooling
Out of use storage tanks	Nesulisieceived coolingdid not receive cooling
Homes of this era may have additional environmental	
hazards/concerns.(i.e., lead, asbestos, etc.) that are not visible to	Course of Action:
the inspector	Ourse of Auton.
Course of Action:	
Decommend further evaluation by an appropriate contractor	
Recommend further evaluation by an appropriate contractor before any renovations of the property.	

Course of Action: Have a heating / cooling or landscaping contractor evaluate and repair as needed.

### **Electrical**

Main Service Entrance	Location Basement	
Location:UndergroundOverhead wires	Service Panel Rated 12.5 Amps	
Overhead Contact Hazards observed:		
obstructed / threatened / touched by tree / branches have hydro	Main Disconnect: 100 Amps	
or a tree surgeon correct situation before damage occurs	Circuit breakerFusesKnife switch	
	LocationMain panel boxOther	
Meter	a 100 A X Circuit Persion Fuers	
Service cable rated: 200_Amps	Service Size Amps Circuit Breaker Fuses 110-120 volt circuits: (number) 15A 20A 30	
Rated110/120 Volts220/240 Volts	220-240 volt circuits: (number)	
W (# wires in service)	20A30A40A50A60A70	
Location: right ride	Branch wiring	
Location.	Copper AluminumKnob & Tube	
Distribution	BX Cable (Metallic sheathed) Romex (Non-metallic	
Outlets, switches, lighting as observed and evaluated, throughout	sheathed) Not determined	
the home. Random tested outlets, wall switches & installed lighting	As observed:inside panel box	
and found the following evidence:	Circuits labeled?YesNoSome	
no deficiencies were detected3 holes(Says grounded)	Panel has been upgraded from original	
	Sub Panels	
Material CopperAluminum Knob & Tube	Panel RatedAmps; Service SizeAmps	
*Please note that Aluminum and/or Knob and Tube wiring may exist within the	Location	
homes' system and not be visible to the inspector or reported due to the limited		
nature of such an inspection. Inspector cannot determine percentage of older wiring.	Defects:	
	More than one wire attached to a circuit protector, have	
Defects:	evaluated for safety by electrician	
Ungrounded outletsReversed polarity	Abandoned wire(s) Connections in panel box	
Hot Ground reversedDead outlets Open groundOpen neutralOpen hot	Non-standard installation / upgrade, further evaluation	
Open air connections	Water stains Rust	
Missing safety covers on switches, outlets and junction boxes	Dead insects, may indicate cable entry not sealed properly	
Loose connections Loose boxes Loose receptacles	Unprotected panel openings, recommend closing down	
Lights did not light, missing or broken bulbsFlickering lights	Overloaded circuitsOverfused breakers / fuses	
Switches for which use not determined (frequently noted)	Loose connectionsinto the boxwithin the box Damaged sheathing	
Loose hanging wires / otherwise dangerous conditions.	Discoloration of wires in panel, may indicate overloaded circu	
Bare bulbs near / touching storage items, possible fire hazard Move wires off heating ducts (secure)	Panel location non-conforming, needs to be addressed	
Lighting at staircases is not sufficient		
In staircases with 3 or more steps, switches are not	Course of Action:	
located at both the top and bottom of staircase.	Have an electrician install Arc Fault Interrupter (AFCI)	
Decora style switches and outlets noted throughout system,	protection Panel may be overloaded, have evaluated and repaired as	
have checked for proper installation with aluminum wiring	needed	
Outlets with 2 slots (Older ungrounded style)  Non-standard electrical noted	Have an electrician check panel and rectify deficiencies as	
_	needed.	
Interior grade wiring noted on exterior Improper use of electrical cords	General Limitations	
	X Concealed electrical components cannot be inspected	
Course of Action:  Have an electrician check entire system and rectify	Main disconnect cover could not be removed, common	
deficiencies as needed.	Panel cover could not be removed due to accessibility,	
ESA certificate may be recommended or required due to	recommend correct Power off insomeall areas	
aluminum or knob and tube wiring	No access to:	
with the same of t	In most cases, grounding termination point is not visible.	

Course of Action: Have an electrician evaluate and repair entire system as required

Page 16 of 38

## Plumbing

Water Supply	Waste System
Entry Location Basement near laundry	(roof)
> Public	Pipes:ABS PlasticCast IronCopperLead
Meter Location Basement dryer	Galvanized Steel Brass Not Visible
Private	Pines observed by cement
Location of wellhead	Galvanized Steel Brass Not Visible  Pipes observed  Main waste line clean-outs were were not observed
	Cheater vent(s) noted
Main Shutoff valve: at entry	Ventingwaswas not observed extending through roof andwaswas not seen in attic
Supply Pipes: Copper Plastic Galvanized	'S' traps noted in drainage system, should be rectified
Brass Lead Could not determine	No 'P' traps visible add at /qun
Conditions requiring attention:	Conditions requiring attention:
	Leaks in waste system:
Distribution Pipes:CopperPlasticGalvanized	None notedactive leaksdry leak type stains
Brass Lead Kitec Unknown metal	were observed
Conditions requiring attention:	Odour noted at, have evaluated by
	plumber
	Discharge
Leaks in water supply systemNone noted	PublicPrivate
Rust / Corrosion noted	Reported byVendorRealtorNot Determined
Nust / Comosion noted	Not Determined
	Didili lilio callo di
Hose Bibs	
NumberNoted	Waste Ejectors
When turned on water came out, when turned off the	None Noted
water did did not shut off fully.	Drain or waste ejector pumps were observed
When turned on water did not come out	Location
Not tested, because	When water was run the pump(s)did did not
Interior:	seem to pump out the waterSlow drainage was noted.
Hose bib shut off valve(s) located	Change ejector pipe to PVC/ABS
	onange ojector pipe to i verribe
	Domestic Water Heater
Frost protected, interior shutoff may not be required	Location basement
Functional Flow	RentalOwnedunknown
TestedNot Tested because	Estimated age / year 2008
	Make: G J W
Method: With multiple fixtures running, flushed toilet(s)	GasElectricOilPropane
to over stress flow, observed decrease in flow:	Water on Demand systemIntegral with heating system
minimalacceptableexcessive	Water on Demand system Integral with heating system Rated Capacity gallons / Liters, which is generally
	ample for aboutpeople, depending on usage.
Hot Water Output:	Safety pressure release valvewaswas not observed
Hot water was was not received at hot water faucets	anddiddid not have safety extension down to floor.
	No Some Extensive rust / corrosion / water
which were operated, in random testing, indicating the system	noted at base of unit indicates unit is leaking.
is is not providing hot water to these faucets.	noted at base of unit indicates unit is leaking.
After aboutminutes of running hot water at	NA
sink faucet, water coming from faucet was	Vent Pipe:doesdoes not slope or rise to exhaust
hotwarmcold.	pipe looseconnection(s) loose
	rusted or deteriorated
	joint to exhaust in need of repair
Additional Comments or Issues:	
Auditional Comments of Issues.	

Course of Action: Have a plumber or other appropriate contractor repair / replace items noted as needed.

# Heating

Distribution Ductwork / Registers Unobserved Radiant Baseboard heaters Thermostat(s) on units on wall Radiators Bleed valves Leaks / Corrosion Heat equal at both ends, indicates proper distribution within unit Boiler system: pressure release valve extension missing Heat supply & return PIPES: Copper Galvanized Iron Plastic Unknown material Observed in: basement crawlspace attic some most pipes not visible Heat Distribution: was was not found in each room - add as needed Distribution missing from: Heat Recovery Ventilator (HRV) noted: working properly Recommend maintenance Recommend service Course of Action: Clean Ducts Insulation on heating pipes/vents, recommend test for asbestos
Seal gaps/joints at ductwork and plenum to maximize the efficiency of distribution system.
Heat Exchanger  Heat exchanger is hidden from view, inside the unit, and therefore cannot be inspected. The following evidence suggests that the heat exchanger may be defective
Filters Air Filter in warm air heating/cooling unitWashable Disposable Electronic HEPA Location at furnace in return grillNot installed properly to correctly filter air
None noted, have it located and evaluated or have installed by heating contractorHeating contractor should rectify defectsRecommend non-allergy type filterFilter appears clogged/blocked replace/clean  Oil Line Filter: Located near entry into basementnear oil tanknear furnace Oil filters should be serviced by a heating contractor annually along with the oil heating unit.
Humidifier None noted Location:return ductheating ductFilter appears cleanAdjust water level
WorkingNot workingDisconnectedParts Missing humidifier should be replacedDrum type humidifier, recommend replace with drip type Humidistat Located:

Course of Action: Have a heating contractor rectify any defects noted above.

Page 20 of 38

## **Basement & Crawl Space**

	Basement	Basement Ceilings
	Percent of lowest level	Exposed to viewPartial view
1	Finished Partially finished	Ceilings finished?No
	Exterior access / egressNone notedDirect walk out	Evidence ofPreviousActive leak
	Up exterior stairway bulkhead	
	op oxionor claiming, asserta	Crawl Space
	Formulation weller Covered Visible	None noted // Percent of lowest level
	Foundation walls:CoveredVisible Approximate percentage visible	Not Accessible
	Limitations to a thorough inspection:	Entered Not Entered, because too low
	StorageInsulationWalls finished / drywall / painted	The same of the sa
_	Visible areas:BlockConcreteBrick & Mortar	Floors:dirt
	Stone & MortarStucco over unknown	Ventilation:notednone noted (add Ventilation)  Type:wall ventsvents into basement
	Condition:	Type: wall vents vents into basement
	Satisfactory	Recommend adding ventilation to this are to prevent
	Evidence of previous wall repair	condensation / moisture problems
	Evidence ofPreviousActive leak	Additional ventilation recommended
	Defects noted:	Evidence of moisture; determine source and repair as needed
	Settlement cracksMinorMonitor over time	
	Significant, have a mason repair	Insulation observed:YesNo; Adequate?YesNo
	Have cracks / leaky areas repaired to prevent ongoing leakage	Vapour Barrier: on warm side of insulation
		None notedInstalled improperly
	- 4 Fl	Moisture Evidence:PresentNot noted
	Basement Floors	Water Penetration Evidence:notednone noted
		Water Penetration Evidencenotednote noted
	concretedirt	01.1 01
	Covered withtile sheet goodscarpetingpainted	Slab on Grade
	Hardwood / softwood / laminated wood	Not ApplicablePercent of lowest level
		concrete wood unknown / not visible
	Limitations to a thorough inspection:Storage	slab:at about grade levelslightly above/below grade
(	Floors finished / coveredExcessive Furniture	The support system below grade is not observed and is unknown.
	Approximate percentage visible	The exterior perimeter of the slab, where visible, cracks
	Satisfactory	werewere not notedNo areas visible
	Defects:	Exposed interior floor coverings are of: concrete vinyl
	Settlement Cracks in floor were noted which appear to	wall to wall carpethardwoodsoftwood carpet less than wall to wall in coverage
	be:older	Observedbrokenwarpedrippled
	small, probably not major defects at this time, which	floor coverings, which may indicate cracks in the slab.
	should be monitored over time to see if they worsen	IIOOI COVERINGS, WINCH THAY INGIGATE GRACKE IN the Graze.
	larger major defects	Floor Drainage
	showing differential settlementheaving	Floor Drainage
	Evidence suggests hollow under floor	Floor Drainage observed: (none Visible)
	Evidence ofPreviousActive leak	YesNo did not have protective perforated cover
	- Voussel	diddid not have protective perforated cover Trap primer noted?YesNo
	Moisture Evidence:PresentNot noted	Evidence of trap cracked / broken
	Water Penetration Evidence:notednone noted	Recommend install backflow preventer
		2.11-
	Exterior Support Piers	Cold Room
	Not Applicable	Not Applicable
	Support columns ofMetalConcreteWood	Install/replace weatherstripping at door
	Stone Block Brick	Venting installedventing blocked, open and leave active
	were observed under the rear addition	No venting, proper venting to be added
	Support columns condition looked Satisfactory	It is not recommended to finish or partially finish a cold room.
		Revert area to original state.
	Additional Comments or Issues:	

Course of Action: Have a masonry or other appropriate contractor repair the above items as indicated.

Page 22 of 38

#### **Water Penetration & Internal Structure**

Water Penetration	Foundation Structure
No signs noted	Joists
Evidence indicates a one time flooding	Not visible
Some extensive evidence of ongoing water penetration	WoodSteel
was observed	
	Condition good defects noted, see below
Evidence observed:	
Water stains on: On walls,at base of wallfloors	Span and beams appear adequate
On walls,at base of wallfloors	Defects Observed:
base of stairsaround furnace	Cracks / cuts that reduce effectiveness, repair
EfflorescenceRot	Joists span too large, add additional support
Microbial growth / mildew	Rot on joists has reduced strength, repair
Rust on nail heads/ baseboard heaters, etc.	Evidence of sagging floors that is,
Sump pump, see section	Minor / older, monitor over time for changes
Wall board damaged	Movement appears to be recent and/ or ongoing, add
Damp or wet floor coverings	additional supports
Lifting tile	Add (#)joist hanger(s)
Other	7-11-1 (11)
Otilei	Columns
imitations to inspection:	Not visible
Limitations to inspection:	Wood steel poured concrete block / brick
Subfloor & carpetStorageFurniture	Appears to have been altered/removed have evaluated
Course of Action:	Condition:
Overall, stains indicate previous flooding	Columns appear sufficient and in good condition
Further evaluation necessary	Columns appear to have shifted, repair immediately
Repair current leak issues noted	Defects observed:
Further evaluation and testing for possible mould recommended	Rot
and remediation work performed as required)	Cracks have reduced strength, add additional support
General Dampness	Insect infestation appears to have compromised columns,
General Damphess	
V	repair immediately
None noted	Market Control of the
Feels dampSmells damp	Sump Pump
Dehumidifier noted	None noted
Location:	
Dehumidifier was running during inspection	Location:pedestal
Evidence that dehumidifier running continuously	Running continuously
Recommend use of dehumidifier in basement	Running continuously
Recommend use of denumidifier in dasement	Activated Not working
	ActivatedNot working
Basement Ventilation	Could not test unitNo water in the hole
	Not plugged in (Electrical)
None noted	Recommend backup system or alarm
None noted	Operating properlySlowReplace
Type	operating propertyreplace
Type:	Discharge
Louvered wall vents	Exterior Storm drain Unknown Sewer connection
Window	ExteriorStorin drainOnknownSewer connection
Area open to main and / or upper floors (open stairwell)	O
Exhaust fan	Course of Action:
Air Exchanging unit	repair/replace
	install sump pump
Other	Redirect discharge
Other	
Course of Action:	install check valve
Course of Action:	
Course of Action: Add additional ventilation to reduce condensation / moist air	
Course of Action:	
Course of Action: Add additional ventilation to reduce condensation / moist air	

Course of Action: All defects noted above should be corrected and/or monitored by an appropriate contractor

# Laundry & Wet Bar

Laundry Area	Laundry Tub
	None noted
No laundry provisions noted	
Location: BasementMain floorUpper floorIn/near bedroomsIn bathroomIn/near kitchen	Tub State State State
In/near bedroomsIn bathroomIn/near kitchen	PorcelainSteelPlasticConcrete
	Tub damaged / cracked, replace
Appliances: Laundry	Formater
Clothes Washer ×C73401499	Faucets: Faucets hot and cold working properly
Clothes Washer	Faucets do not shut off fully
None noted Francisco	Hot and cold reversed, have a plumber repair
None noted  Brand  Age: Newer Older Midlife	Not and cold reversed, have a plumber repair
Age: Newer Older Midille	Drain securenot secure
Connections for water & drain were noted	
	No leaks noted
Connections not visible Condition of water hoses:SatisfactoryReplace	Leaks noted at faucetsbelow tub
Condition of water needs.	Leaks at water lines
Electrical OutletGroundedNot grounded Replace outlet	
In use during inspection, performing normal cycles	Wet Bar
Operated one cycle, heard water come in, splash, spin	None noted
and pump out	
Not operated	Location:
Course of Action:	Wet barAdditional sink only
Have an appliance repair contractor repair noted defects.	Other
Clothes Dryer	Sink
Clothes Dryer XD/351 (65)	Sink PorcelainSteelPlasticConcrete
Brand Prigidaire	
Brand	Drainage pipes
Clastic Con	CopperPlasticCast IronLead
Electric Gas Connections were noted Not Secure	Galvanized Steel
Connections were noted Not Secure	Culvulized otto
Vented to:Not vented properly, redirect	Leaks noted
Age: Older Midlife	None noted
AgeNewerOlderWilding	Above the sinkbelow the sinkAt taps
Unit checked for spin and drying heat	
In use during inspection, performing major functions	Counter top
Not operated	Plastic LaminateCeramic TileWood
Not operated	areare not secure
Course of Action:	loose (unsafe)missinglarge areas heat
Change dryer vent to metal	scorched or damaged
Vent appears clogged / dirty, requires cleaning (All dryer vents.	Stored items affecting visibility of counter tops at time of
require regular maintenance, see preventative maintenance booklet for more	inspectionminimalabout normalextensive
information	mopodionminimaldboat notifiedone.co
Have an appliance repair contractor repair noted defects.	
11	Electrical: Wet Bar
Electrical: Laundry	Listing. Hot but
Ground Fault InterrupterNone Noted	Ground Fault InterrupterNone Noted
Recommend add GFI's for safety	Recommend add GFI's for safety
Additional Comments or Issues:	

Course of Action: Have an appliance, plumber or other appropriate contractor evaluate and repair as needed.

Page 26 of 38

Copyright © 2015 Lighthouse Inspections

## Kitchen & Appliances

Location	Range / Cooktop 126812670 N
Basement XMain floorUpper floor	Brand: Magic Chet
	Style: Free Standing Built in
Cabinets	Fuel type:ElectricGasOther
Wooden Plastic Laminate Other one of life	Age:NewerOlderMidlife
Cabinets are are not secure end of life	Not operated In use during inspection, indicating portion being used is
Doors and drawers:function as expectedloose cabinetsmissing hardwaremissing door or drawer fronts	performing its major function
broken drawerswarped doorsadjust doors	Operated and found that # burners gave heat and
Stored items affecting visibility as to condition at time of inspection	#did not give heat
were:MinimalExtensive	"uid not give neat
	Oven
Counter Tops	Brand:
Plastic LaminateCeramic TileGranite/Marble/Corian	Part of the stove Built in
areare not secureloose (unsafe)missing	Fuel Type:Electric GasSelf cleaning(Not checked)
large areas heat scorched or damaged	Age:NewerOlderMidlifeSee Stove
Stored items affecting visibility of counter tops at time of	Not operated,
inspectionminimalabout normalextensive	In use during inspection, indicating the portion being used is
Sink	performing its major function
Stainless Steel Porcelain Plastic	Bake and broildiddid not give heat when turned on.
Undetermined material	Bake and broildiddid not give heat when turned on.
Ran the water and found leaks None notedAbove the sink	Refrigerator, 0 12 82 08 07 G
below the sink. Have leaks repaired by plumber	Brand: Magic Chef 120200118
Sink chipped/cracked. Stopper/strainer waswas not noted	Age:NewerOlderMidlife
	In use during inspectionOperated
Disposal	Not operated
None noted	Items in cooling section felt cool, in freezer section felt frozen
Brandhorsepower	-indicates doing major functions
Leaks noted?YesNoHave leaks repaired by plumber	Features:lce makerWater & Ice through doorFrost Free
Tested unit, results:	Magnetic Seal:Damaged / Broken
Ventilation	Dishussher 37/537/3
	Brand: Magic Chef 376535621
None Noted, other than doors and windowsFan integral with a built-in Microwave or cooktop	Age: Newer Older Midlife
Exhaust fan appears to vent to exterior	
Recirculates air within the room Light	Operated In use during inspection Not operated items/storage in machine
When the components were turned on, they seemed to	HeardDid not hear water come in, splash and pump
perform their major function.	out, indicating that the appliance is doing its major functions
Fan sounds excessively noisy	Recommend relocate drain to sink side of P trap
Filters: ObservedNone Noted	Recommend secure unit
	Built in Microwave DU0750025
Electrical	Prand: Magic Chef
Ground Fault InterrupterNone Noted  Recommend add GFI's for safetyat sink	Age: Newer Older Midlife
Inadequate number of electrical outlets	Heated container of water, indicating does major function
madequate number of distilled states	Too close to cooktop, repair as needed
Kitchen Floor	Not operated,
LaminateVinyl TileCeramic Tile	Other Appliance
WoodCarpet	None noted
Normal amount of bounce excessive bounce noted	Brand:
Have a flooring contractor correct any defects or	Operated Not Operated
deficiencies noted in floor.	

Course of Action: Have an appliance repair or other appropriate contractor repair any deficiencies noted above.

Page 28 of 38

#### **Bathrooms**

BATHROOM 1: Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    None noted Noted atTubShowerSinkBidet    Re-caulk as required Leaks:None noted Noted atTubShowerSinkBidet    From fixtureFrom faucets Electrical:Ground Fault Interrupter Install GFI    No receptacles	BATHROOM 2: Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet    From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI    No receptacles
Plumbing noted on exterior wall, unacceptable	Plumbing noted on exterior wall, unacceptable
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastened YesNo Toilet:Flushed, Feels adequately secured YesNo Bidet:None notedTurned on     Feels adequately fastened YesNo Damage:None NotedCracked / Chipped Noted at Tub Shower SinkBidet Taps Floor:VinylCeramic Tile	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic

Have all above items corrected by a plumber or other appropriate contractor before items deteriorate further.

## Fireplaces & Common Safety Devices

Fireplace # 1	Ground Fault Interrupter (GFI) Protection
None noted	No GFIs noted in house wiringGFI(s) noted in panel box
Location	GFIs noted in branch outlets GFI(s) noted on exterior
MasonryMetal prefabricatedWood Stove Insert	
Gas Insert Working	Testing & Results:
Firebox:MetalMasonry	using an electric tester plugged into outlet
Firebrickloose mortar	using test button on GFI. All devices testedDIDDID NOT trip, as expected.
Abnormal openings (Cracks, missing grout, etc.)	All devices testedDID MOT trip, as expected.
Flue:Dirtysharedmissing linerClearance	0
Damper:Opened and closedCould not open & close safely	Course of Action:
Broken or missing parts	GFIs should be retested & repaired/replaced by electrician and more added, as needed.
did did not observe flue liner	GFIs should be installed
Combustion air supply:InteriorExterior air  Limitations:Fire burning area blocked, unable to inspect	
Pilot light was off during inspection	Smoke Detectors //
Course of Action:	None Noted have an electrician install immediately
Have WETT Certified contractor clean, test, evaluate and	None Noted, have an electrician install immediately
certify before use	#2_Smoke Detectors
Have fireplaces cleaned annually by a chimney sweep	V. Net Tested as may be connected to wired / wireless
	X Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm company
Fireplace # 2	
None noted	before sleeping in house.
Location	5.4.6
MasonryMetal prefabricatedWood Stove Insert	Course of Action: Install additional smoke detectors
Gas Insert Working	upper floor main floor Basement
Firebox:MetalMasonry	Within 5 feet of bedroom doors
Firebrickloose mortar	Replace smoke detectors
Abnormal openings (Cracks, missing grout, etc.)  Flue:Dirtysharedmissing linerClearance	Relocate smoke detectors
Damper:Opened and closedCould not open & close safely	
Broken or missing parts	X Test smoke detectors monthly
did did not observe flue liner	X Test smoke detectors before sleeping in the house
Combustion air supply:InteriorExterior air	
Limitations:	Carbon Monoxide (CO) Detectors
	Carbon Monoxide (CC) Betesters
Fire burning area blocked, unable to inspect	No permanently installed CO detectors noted
Pilot light was off during inspection	# CO Detectors
Course of Action:	#CC Delicators
Have WETT Certified contractor clean, test, evaluate and	X Not Tested as may be connected to wired / wireless
certify before use  Have fireplaces cleaned annually by a chimney sweep	alarm system in house, they should be tested by alarm company
have illeplaces cleaned allidally by a clining sweep	before sleeping in house.
Mand Ctave	Install CO detector in hall on all sleeping levels at knee level
Wood Stove	
None noted	Replace Carbon Monoxide detectors  X Test CO detectors before sleeping in the house
Location	
Fire burning at time of inspection, unable to inspect	Interior Fire Cariables Cretem
Have WETT Certified contractor clean, test and evaluate	Interior Fire Sprinkler System
Have clearances of wood stove and flue pipes evaluated by a	None Noted
WETT Certified Contractor	Noted, have evaluated for proper operation
Have WETT Certified contractor evaluate condition and	Sprinklers are not tested, because to do so would cause flooding and damage to furnishings in the home. Have system evaluated by an appropriate contractor.
clearances of wood stove and flue pipes	

Course of Action: Have an electrician install safety devices before sleeping in the home

#### **General Interior**

Ceilings	Doors
DrywallWoodMetalAcoustic ceiling tilesPlaster overWood lathMetal meshwall board	Mainly door types of:Hollow coreWoodPlasticHinged one sideBi-foldLouveredMirrored
Unknown backer material Appears recently painted / paperedNail pops were noted No major defects were noted Water stains inarea Appears dry, monitor over time The following major defects were noted:	Sliders  Defects noted:Some adjustments could be made to the door fitDoors do not open and close easilyDoors or hinges feel/look looseDoors with holes & broken parts
	Doors missing from opening which normally would be
Walls  Drywall Wood Panel covered  Plaster over: Wood lath Metal mesh wall board	expected to have doors. Doors with missing, broken or damaged hardware / locks
Unknown backer materialUnknown materials	Windows
No major defects were noted Appears recently painted / paperedNail pops were noted The following major defects were noted:	Primarily the following types of windows were observed: Single hungCasement SlidingAwningHopperFixed panes  SomeMost seem to have insulated glazing (glass)
Floors	They appear to be made of:WoodMetalPlastic
Wall to wall carpetRoom sized rugsHardwoodLaminated WoodPlywoodSheet goodsVinyl tilesCeramic tile When bounced on,a normal amount of bounce was notedexcessive bounce was notedupper floor, monitor for anguing movement.	A combination of materialsUnknown  Random tested windows and found Window SashDoDo not open or close under normal pressure
ongoing movement  Trim	Defects:
None noted (base of walls, around doors & windows)  Mainly, material type of:WoodPlastic  Trim isPaintedStainedUnfinished Paint or finish was observed to be peeling.  Trim was observed to beloosemissing in a fewmost places	Broken glassBroken, rotted or loose sash piecesBroken or defective counter balance devicesMissing handles, locks, and hardwareMissing screensDamaged screens, replaceStains, indicating leaks or condensationFogged up / Condensation notedbroken thermal seals
Stairs, Balconies, & Railings  To Basement To Attic Between living levels  Felt solid under foot, rise and run felt about even	Recommend replace windows for energy conservation
Trip hazards observed:	Skylights and Roof Windows
Uneven rise and run from step to stepWeak or springy treads or stringersShallow treads noted	None noted from interior Appear fixed Operated did not operate Results:
Loose handrails noted onstairs Loose carpet or tread coverings Large openings in rail system should be closed down Steep steps (rise too high) No handrails noted on Basementstairs  Course of Action:Add handrail for safety Railings too low by today's standards, add / adjust for safety  Additional Comments or Issues:	SomeMost seem to have insulated glazing (glass)  Leaks (around unit):None noted Small stains noted Excessive staining/damage noted  Condensation/Leaks (abutting glass)None noted Small stains notedExcessive stains noted Active water penetration observed
Additional Comments of Issues.	

Course of Action: Have a carpenter or home improvement contractor correct defects noted above

# Attic & Ventilation

Attic Access	Attic Ventilation
No AtticFlat roofCathedral ceiling	No ventilation noted, it may or may not exist
No Access Blocked by storage items	Tomas
Otalian and Otalian on INTERIOR maga	Type: Ridge vent
Stairs, see Stairs on INTERIOR page	Roof vent
Pull down in	Gable end vent
Access Hatch in	Soffit / Fascia vent
	Turbines
Results: Limited viewing, looked in through opening ONLY	Whole house fan
Due to:low headroomno walkway/floorStorage	Other
Jue to:low neadroomno warkway/noolStorage	
Entered, walked from end to end	Vents obstructed by:Insulationnest / hives
Entry blocked by excessive storage which also	
revented sufficient viewing of attic area.	
NOVOITION CAINGIOTH FLOWING C. CLEEC C. C.	Exhaust venting fans noted in ceilings below attic floor with
Attic Hatch:	nothing noted in attic to indicate they vent directly to exterior.
Insulate Weatherstrip access hatch	- / ·
Moisture / Mildew noted at hatch opening area, repairs needed	Defects:
	Inadequate ventilation, increase venting
	Exhaust fans from interior end in attic and must be
Framing	directed to exterior.
RaftersTrusses	Remove insulation that is currently blocking vents, install soff
Sheathing	baffles
Structural panelsSpaced boards	Soffit vents missing baffles, should be installed
Defects:	
SaggingBuckling	
CrackingRot	Course of Action:
Delaminating	
	<u> </u>
Course of Action:	
Localized defects, monitor over time	Moisture & Water Penetration
Add or secure structural supports	None noted
Seal party / fire walls	
<del></del> /	Evidence observed in attic:
	Dark stains on framing
Attic Storage	Microbial growth / mildew
V	Rust / corrosion on roofing nails
Not recommended	
Limited storage Attic fully floored	Water damage
Attic fully libored	Water stains
	Condensation evident on exhaust pipes
	Course of Action:
	Insulate exhaust vents in attic
	Increase Insulation on pipes
	Have a contractor inspect and repair/rebuild as needed
	Further evaluation and testing for possible mould recommend
	(and remediation work performed as required)
Additional Comments or Issues:	

Course of Action: Have a roofing or other appropriate contractor evaluate and repair as needed.

Page 36 of 38

#### Insulation

Attio	Ductwork
Attic	
None notedAttic could not be accessed	None noted
Fully flooredSome observed, mostly obscured	Somemost ductwork in unconditioned spaces
Form:	was observed to be insulated.
Batt / BlanketLoose FillRigid Board	Insulation appears to beadequateinsufficient
Foamed in Place	Observed:CondensationRust
Type:	Uninsulated ducts should be insulated for energy conservation and to
Glass FiberWood ShavingsMineral Fiber	prevent condensation and resultant damage.
Cellulose FiberUrea Formaldehyde Foam (UFFI)	
Plastic/Foam BoardVermiculite, test for Asbestos content	Pipes
	None notedHeating cables
Other	Somemany pipes believed to be carrying heated
Location:RoofBothother	or chilled water or coolants in unconditioned spaces were
FloorRoolBottlother	observed to be insulated.
Estimated thickness inches Unknown	Insulation appears to be adequateinsufficient
Estimated thicknessinchesUnknown	
Estimated Posters /P	Uninsulated pipes should be insulated for energy conservation and to
Estimated R-valueR	prevent condensation and resultant damage.
Defects:	
WetCompressedMildew / fungus	Walls
Evidence of past or current rodent infestation	Not determined
Insulation appears, smells or feels damp/wet, replacing	Through hole in wall(located),
should improve efficiency & reduce allergies.	saw type of insulation.
Low / bare spots in insulation, recommend additional insulation	
Vapour barrier:None NotedNot visible	Removed #exterior wall outlet covers on interior
Plastic Kraft Paper Polyethylene	of house and saw
Other Not determined	While the above does not determine that the walls are or are not insulated,
Barrier is located on warm side of the insulation	it may give an indication of what is in the walls. Sometimes insulation
Barrier is vithin insulation or on cold side, have repaired	is placed behind electrical boxes and nowhere else.
Exhaust pipes from interior:	To placed berining diedared some and normale elect.
Adequate insulationwetcondensation	Puilding Underside
	Building Underside
Clearances	Not Applicable
Adequate around pot lights, fans other mechanical items	None noted
Electrical wiring observed within or on top of insulation, have	From within a crawl space / basement, under floor of the
secured.	lowest living areainsulation was observed.
Course of Action:	
Adding additional insulation should be considered to	Estimated thicknessinches thick
increase energy efficiency of home.	Estimated R-value ofR.
Additional Comments or Issues:	
Course of Action: Have an appropriate cont	ractor replace or add insulation where needed.
General	Limitations
General Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:	Limitations the view of the inspector. In addition to the standard obstructions, the
General Normal furnishings and floor, ceiling, and wall coverings will obstruct	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior
General Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the house
General Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior  plantings too close to building snow and ice buildupvines on the building	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the house
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior plantings too close to buildingvines on the buildingdebris, leaves, brush, wood or other items piled against	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the housenormalminimal,excessive  Stored items:
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior plantings too close to buildingsnow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against exterior of building	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the housenormalminimal,excessive  Stored items:
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior plantings too close to buildingsnow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against exterior of building Other	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the housenormalminimal,excessive  Stored items:throughout the house,basement,atticnormalminimal,excessive
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior plantings too close to buildingsnow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against exterior of building	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the housenormalminimal,excessive Stored items:throughout the house,basement,atticnormalminimal,excessiveInterior appears recently painted/papered
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior plantings too close to buildingsnow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against exterior of buildingOtherExterior appears recently painted/sided	Limitations the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the housenormalminimal,excessive Stored items:throughout the house,basement,atticnormalminimal,excessiveInterior appears recently painted/paperedRenovation work recently done
Normal furnishings and floor, ceiling, and wall coverings will obstruct following items further limited the inspection:  Exterior  plantings too close to building snow and ice buildupvines on the building debris, leaves, brush, wood or other items piled against exterior of building Other Exterior appears recently painted/sided	the view of the inspector. In addition to the standard obstructions, the  Interior  Furnishings throughout the house

Page 38 of 38